

<b>Summary of Distribution Circuit Field Inspection by ICC Staff</b>			
<b>Utility:</b>	<b>MidAmerican</b>	<b>Date:</b>	<b>8/14/02</b>
<b>Circuit:</b>	<b>13-108-1</b>	<b>Inspector:</b>	<b>Larson/Rockrohr</b>
<b>Gen. Notes:</b> Area was generally rural - several non-farm homes in area.			
<b>Map No.</b>	<b>Item Description</b>	<b>Photo(s)</b>	<b>Location</b>
1	Guy wire without insulator		Three poles east of substation
4	Split top - minor	1	About 601-699
5	Missing brace	2	About 340-296
6	Guy wire without insulator - several	None	about 235-007 to end of line