

**Illinois Commerce Commission
Pipeline Safety
Exit Meeting Documentation Form**

Operator:	AMEREN ILLINOIS COMPANY
Inspection Unit:	AMEREN ILLINOIS COMPANY - Tuscola
Date of Meeting:	09/28/2012
Pipeline Safety Analyst:	RANDY STEWART
Person Notified:	DALLAS JETT

Issues Identified/Amendments/Probable Violations:

ISSUES FOUND:

192.365(b) The meter set at 303 Holiday Drive was noted to have a buried stopcock. A brick patio had been constructed around the service line to the top of the stopcock leaving only the top of the nut visible. Ameren exposed the service line and replaced the stopcock. While performing a follow-up inspection a class 3 leak was detected at the regulator vent. The customer was not at the residence. The regulator will be replaced. At the close of this audit a pipe to soil reading had been obtained, and the regulator is in the process of being replaced.

ISSUES CORRECTED:

NO ISSUES CORRECTED.

NOTICE OF AMENDMENT:

NO NOAs FOUND.

NOAs CORRECTED:

NO NOAs CORRECTED.

NOTICE OF PROBABLE VIOLATION:

NO NOPVs FOUND.

NOPVs CORRECTED:

NO NOPVs CORRECTED.

Pipeline Safety Analyst Signature:



Operator Representative Signature:


