

**Illinois Commerce Commission
Pipeline Safety
Exit Meeting Documentation Form**

Operator:	AMEREN ILLINOIS COMPANY
Inspection Unit(s):	Springfield
Date of Meeting:	04/30/2014
Pipeline Safety Analyst:	Kevin Hecker
Exit Meeting Contact:	John Sigler

INSPECTION FINDINGS

Standard Inspection - Field Audit

Issues(s) Found:

[192.706] - During the leak survey of Ameren's transmission line on April 27-29, 2014, staff walked with the surveyors from the Springfield take point approximately where the line turns north toward Ameren's Lincoln Storage facility. On April 29, Staff requested that the line be located in 2 sections of plowed field to compare the path of the surveyors to the actual location of the pipeline. In the first instance along Highway 124, the walked survey was approximately 5-6 feet from the actual line. In the second instance in a plowed field near Val-E-Vue subdivision, the deviation was approximately 30 feet.

Notice Of Amendment(s) Found:

[NO NOAS FOUND]

Notice Of Violation(s) Found:

[NO NOPVS FOUND]

PAST INSPECTION FINDINGS

Issue(s) Corrected:

[NO ISSUES CORRECTED]


Notice Of Amendment(s) Corrected:

[NO NOAS CORRECTED]

Notice of Violations(s) Corrected:

[NO NOPVS CORRECTED]

Pipeline Safety Analyst Signature:



Operator Representative Signature:

