

**Illinois Commerce Commission
Pipeline Safety
Exit Meeting Documentation Form**

Operator:	WHITE HALL GAS DEPT, CITY OF
Inspection Unit(s):	WHITE HALL GAS DEPT, CITY OF
Date of Meeting:	06/11/2015
Pipeline Safety Analyst:	Charles Gribbins
Exit Meeting Contact:	John Harbaugh

Exit Statement

INSPECTION FINDINGS

Standard Inspection - Field Audit

Issues(s) Found:

Code Part [192.479(c)] - Staff found the following services to have atmospheric corrosion issues: 437 Carr Street - atmospheric corrosion found under wrap with metal loss;

Code Part [192.707(d)(1)] - Staff found indication of line markers along the entire right of way that need to have some remedial action taken to replace the signs on the line marker post, were the information is coming off or has faded to the point it can no longer be read. Staff advised the operator to take corrective action.

Code Part [192.479(c)] - The service line located at 347 N. Carr was found to have disbonded coating on the above ground piping.

Code Part [192.479(c)] - The service line at 223 Jacksonville Street was found to have atmospheric corrosion found under the wrap with metal loss.

Notice Of Amendment(s) Found:

[NO NOAS FOUND]

Notice Of Violation(s) Found:

[NO NOPVS FOUND]

PAST INSPECTION FINDINGS

Issue(s) Corrected:

[NO ISSUES CORRECTED]

Notice Of Amendment(s) Corrected:


[NO NOAS CORRECTED]

Illinois Commerce Commission
Pipeline Safety
Exit Meeting Documentation Form

Notice of Violations(s) Corrected:

[NO NOPVS CORRECTED]

Pipeline Safety Analyst Signature:



Operator Representative Signature:

