Exhibit 2.7
Replacement Services

Fiscal Year	Year In Se	Data	Sleeper	Stranger Total	Poplar	Cypress Total	Grand Total
2004	1945	Sum of Removal Cost			32.47	32.47	679.05
		Sum of Retired Cost			47.16	47.16	175.19
	1946	Sum of Original Quantity					6.00
		Sum of Removal Cost					4,963.48
		Sum of Retired Cost					378.78
	1947	Sum of Original Quantity					1.00
		Sum of Removal Cost					77.36
		Sum of Retired Cost					12.72
	1948	Sum of Original Quantity					5.00
		Sum of Removal Cost					1,161.72
		Sum of Retired Cost					238.54
	1949	Sum of Original Quantity					1.00
		Sum of Removal Cost					136.27
		Sum of Retired Cost					22.40
	1950	Sum of Original Quantity			1.00	1.00	5.00
		Sum of Removal Cost			41.98	41.98	2,452.67
		Sum of Retired Cost			60.97	60.97	280.98
	1951	Sum of Original Quantity					4.00
		Sum of Removal Cost					1,363.30
		Sum of Retired Cost					224.09
	1952	Sum of Original Quantity					7.00
		Sum of Removal Cost					1,626.50
		Sum of Retired Cost					293.20
	1954	Sum of Original Quantity					4.00
		Sum of Removal Cost					593.15
		Sum of Retired Cost					134.67
	1955	Sum of Original Quantity			2.00	2.00	5.00
		Sum of Removal Cost			111.23	111.23	1,146.07
		Sum of Retired Cost			161.56	161.56	331.66
	1956	Sum of Original Quantity			1.00	1.00	4.00
		Sum of Removal Cost			58.58	58.58	1,810.85
		Sum of Retired Cost			85.09	85.09	441.89
	1957	Sum of Original Quantity					2.00
		Sum of Removal Cost					268.74
		Sum of Retired Cost					66.73
	1959	Sum of Original Quantity	1.00	1.00			5.00
		Sum of Removal Cost	63.56	63.56			1,369.27
		Sum of Retired Cost	77.49	77.49			403.81
	1960	Sum of Original Quantity					4.00
		Sum of Removal Cost					1,446.21
		Sum of Retired Cost					280.25
	1961	Sum of Original Quantity					2.00
		Sum of Removal Cost					671.95
		Sum of Retired Cost					160.38
	1962	Sum of Original Quantity			2.00	2.00	3.00
		Sum of Removal Cost			118.74	118.74	289.52
		Sum of Retired Cost			172.46	172.46	242.90
	1963	Sum of Original Quantity					4.00
		Sum of Removal Cost					821.19
		Sum of Retired Cost					299.14
	1964	Sum of Original Quantity					4.00
		Sum of Removal Cost					610.32
		Sum of Retired Cost					251.01
	1965	Sum of Original Quantity					5.00
		Sum of Removal Cost					4,486.42
		Sum of Retired Cost					451.16
	1966	Sum of Original Quantity			2.00	2.00	4.00
		Sum of Removal Cost			433.71	433.71	1,340.25
		Sum of Retired Cost			629.94	629.94	828.46
	1967	Sum of Original Quantity					1.00
		Sum of Removal Cost					314.74
		Sum of Retired Cost					129.82
	1968	Sum of Original Quantity			2.00	2.00	4.00
		Sum of Removal Cost			603.58	603.58	874.99
		Sum of Retired Cost			876.68	876.68	1,043.03
	1969	Sum of Original Quantity					1.00
		Sum of Removal Cost					268.63
		Sum of Retired Cost					110.80
	1970	Sum of Original Quantity	1.00	1.00			2.00
		Sum of Removal Cost	82.74	82.74			20,289.48
		Sum of Retired Cost	100.87	100.87			1,015.73
	1972	Sum of Original Quantity	1.00	1.00			1.00
		Sum of Removal Cost	92.30	92.30			92.30

Exhibit 2.7
Replacement Services

Fiscal Year	Year In Se	Data	Streetlight			Streetlight Total	Traffic							Traffic Total	Grand Total
2003	1972	Sum of Retired Cost			112.52	112.52									112.52
	1973	Sum of Original Quantity													3.00
		Sum of Removal Cost													4,127.06
		Sum of Retired Cost													824.33
	1974	Sum of Original Quantity													2.00
		Sum of Removal Cost													10,566.48
		Sum of Retired Cost													476.92
	1975	Sum of Original Quantity													1.00
		Sum of Removal Cost													24,501.78
		Sum of Retired Cost													1,110.53
	1976	Sum of Original Quantity													3.00
		Sum of Removal Cost													1,962.61
		Sum of Retired Cost													656.81
	1977	Sum of Original Quantity													3.00
		Sum of Removal Cost													2,283.65
		Sum of Retired Cost													563.93
	1978	Sum of Original Quantity													1.00
		Sum of Removal Cost													900.42
		Sum of Retired Cost													371.39
	1979	Sum of Original Quantity			1.00	1.00	1.00							1.00	5.00
		Sum of Removal Cost			201.65	201.65	213.31							213.31	2,650.19
		Sum of Retired Cost			245.84	245.84	309.82							309.82	1,477.61
	1980	Sum of Original Quantity													2.00
		Sum of Removal Cost													1,668.42
		Sum of Retired Cost													588.16
	1982	Sum of Original Quantity													1.00
		Sum of Removal Cost													8,930.49
		Sum of Retired Cost													1,139.19
	1983	Sum of Original Quantity													1.00
		Sum of Removal Cost													1,053.15
		Sum of Retired Cost													173.11
	1984	Sum of Original Quantity													1.00
		Sum of Removal Cost													830.98
		Sum of Retired Cost													342.75
	1986	Sum of Original Quantity													1.00
		Sum of Removal Cost													10,571.55
		Sum of Retired Cost													479.15
	1988	Sum of Original Quantity													1.00
		Sum of Removal Cost													14,159.68
		Sum of Retired Cost													641.78
	1989	Sum of Original Quantity													1.00
		Sum of Removal Cost													3,795.18
		Sum of Retired Cost													1,565.37
	1991	Sum of Original Quantity													1.00
		Sum of Removal Cost													1,059.23
		Sum of Retired Cost													174.11
	1992	Sum of Original Quantity			1.00	1.00									2.00
		Sum of Removal Cost			413.35	413.35									2,743.42
		Sum of Retired Cost			503.92	503.92									1,464.99
	1999	Sum of Original Quantity					1.00							1.00	2.00
		Sum of Removal Cost					192.82							192.82	2,017.59
		Sum of Retired Cost					280.06							280.06	1,032.71
	2000	Sum of Original Quantity					1.00							1.00	1.00
		Sum of Removal Cost					192.82							192.82	192.82
		Sum of Retired Cost					280.06							280.06	280.06
	2002	Sum of Original Quantity			3.00	3.00									5.00
		Sum of Removal Cost			585.52	585.52									39,113.94
		Sum of Retired Cost			713.82	713.82									2,460.10
	(blank)	Sum of Original Quantity													2.00
		Sum of Removal Cost													120.01
		Sum of Retired Cost													49.50
2003 Sum of Original Quantity			1.00		13.00	14.00	10.00			2.00	2.00			14.00	363.00
2003 Sum of Removal Cost			82.74		1,456.87	1,539.61	961.94			433.71	603.58			1,999.23	231,413.46
2003 Sum of Retired Cost			100.87		1,776.11	1,876.98	1,397.18			629.94	876.68			2,903.80	28,062.24
Total Sum of Original Quantity			37.00	1.00	31.00	69.00	43.00	1.00		4.00	2.00	18.00		68.00	1,308.00
Total Sum of Removal Cost			1,750.37	197.70	7,036.88	8,984.95	8,949.43	622.43		1,201.95	603.58	2,919.36		14,296.75	##########
Total Sum of Retired Cost			2,133.92	241.02	3,550.37	5,925.31	5,732.01	138.76		1,745.78	876.68	1,917.91		10,411.14	301,562.22

New or Replace	(All)

Exhibit 2.7
Replacement Service Investments

Sum of Installed Cost		Responsible BU						
Year In Service	Size	Alton	Cairo	Interurban	Peoria	Streator	Pontiac	Grand Total
1999	0.75	45,229.24	19,178.71	237,248.19	332,380.54			634,036.68
	1	4,763.69	50.67	31,249.69	51,876.36			87,940.41
	2	2,299.10		13,078.02	14,730.61			30,107.73
1999 Total		52,292.03	19,229.38	281,575.90	398,987.51			752,084.82
2000	0.75	51,543.52	6,499.56	182,495.88	369,324.29	14,873.56	6,025.39	630,762.20
	1	3,896.10	135.43	28,349.26	48,728.42	4,518.21	10,068.36	95,695.78
	1.5	72.87			329.35	102.77	1,170.15	1,675.14
	2	2,104.98	1,146.94	9,818.57	5,321.78	792.53		19,184.80
	4						684.76	684.76
2000 Total		57,617.47	7,781.93	220,663.71	423,703.84	20,287.07	17,948.66	748,002.68
2001	0.75	62,867.31	35,063.21	192,635.25	298,690.20	11,480.74	1,695.69	602,432.40
	1	2,621.01	290.37	10,347.49	60,963.36	9,484.48	26,011.48	109,718.19
	1.5	79.37				188.44	779.19	1,047.00
	2			4,021.38	22,634.17	566.75		27,222.30
	6					45.13		45.13
	8					1,773.39		1,773.39
2001 Total		65,567.69	35,353.58	207,004.12	382,287.73	23,538.93	28,486.36	742,238.41
2002	0.75	59,893.58	13,983.79	164,342.94	394,296.95	40,943.27	133.73	673,594.26
	1	3,202.53	1,351.01	23,919.74	101,817.44	2,442.00	15,205.47	147,938.19
	1.5		719.12		111.23	176.76	7,915.44	8,922.55
	2	1,879.40		2,282.41	24,270.15	482.68	5,366.67	34,281.31
	4						(39.56)	(39.56)
	6					118.41	(39.56)	78.85
2002 Total		64,975.51	16,053.92	190,545.09	520,495.77	44,163.12	28,542.19	864,775.60
2003	0.75	33,350.60	9,943.83	133,533.68	504,508.73	32,017.21	1,801.64	715,155.69
	1	13,273.50	30.13	22,171.37	101,765.58	5,442.94	10,170.92	152,854.44
	1.5						27.46	27.46
	2	3,858.72		5,207.57	14,342.39	2,037.04	824.23	26,269.95
2003 Total		50,482.82	9,973.96	160,912.62	620,616.70	39,497.19	12,824.25	894,307.54
Grand Total		290,935.52	88,392.77	1,060,701.44	2,346,091.55	127,486.31	87,801.46	##########

Asset Type	(All)

Exhibit 2.7
Replacement Hydrants

Fiscal Year	Year In Se	Data	Responsible BU						Grand Total
			Cairo	Alton	Interurban	Peoria	Streator	Pontiac	
1999	1891	Sum of Original Quantity					1.00		1.00
		Sum of Retired Cost					21.91		21.91
		Sum of Removal Cost					412.08		412.08
	1936	Sum of Original Quantity					40.00		40.00
		Sum of Retired Cost					1,206.16		1,206.16
		Sum of Removal Cost					23,112.73		23,112.73
	1938	Sum of Original Quantity		23.00					23.00
		Sum of Retired Cost		367.85					367.85
		Sum of Removal Cost		5,945.57					5,945.57
	1940	Sum of Original Quantity	1.00						1.00
		Sum of Retired Cost	60.84						60.84
		Sum of Removal Cost	104.83						104.83
	1941	Sum of Original Quantity					1.00		1.00
		Sum of Retired Cost					59.05		59.05
		Sum of Removal Cost					50.82		50.82
	1942	Sum of Original Quantity		1.00					1.00
		Sum of Retired Cost		75.42					75.42
		Sum of Removal Cost		22.06					22.06
	1948	Sum of Original Quantity			1.00				1.00
		Sum of Retired Cost			74.24				74.24
		Sum of Removal Cost			327.36				327.36
	1949	Sum of Original Quantity			2.00		14.00		16.00
		Sum of Retired Cost			292.71		1,431.22		1,723.93
		Sum of Removal Cost			311.91		5,684.66		5,996.57
	1950	Sum of Original Quantity		1.00			1.00		2.00
		Sum of Retired Cost		73.19			8.95		82.14
		Sum of Removal Cost		112.09			335.34		447.43
	1951	Sum of Original Quantity		1.00					1.00
		Sum of Retired Cost		88.14					88.14
		Sum of Removal Cost		134.99					134.99
	1953	Sum of Original Quantity	1.00	1.00					2.00
		Sum of Retired Cost	16.36	110.88					127.24
		Sum of Removal Cost	87.00	337.97					424.97
	1954	Sum of Original Quantity			1.00				1.00
		Sum of Retired Cost			79.78				79.78
		Sum of Removal Cost			163.19				163.19
	1955	Sum of Original Quantity			1.00				1.00
		Sum of Retired Cost			97.30				97.30
		Sum of Removal Cost			161.80				161.80
	1956	Sum of Original Quantity					2.00		2.00
		Sum of Retired Cost					401.66		401.66
		Sum of Removal Cost					1,106.81		1,106.81
	1957	Sum of Original Quantity					1.00		1.00
		Sum of Retired Cost					126.12		126.12
		Sum of Removal Cost					354.29		354.29
	1962	Sum of Original Quantity					1.00		1.00
		Sum of Retired Cost					114.28		114.28
		Sum of Removal Cost					440.15		440.15
	1965	Sum of Original Quantity					1.00		1.00
		Sum of Retired Cost					209.40		209.40
		Sum of Removal Cost					312.59		312.59
	1968	Sum of Original Quantity					1.00		1.00

Asset Type	(All)

Exhibit 2.7
Replacement Hydrants

			Responsible BU						
Fiscal Year	Year In Se	Data	Cairo	Alton	Jacksonville	Peoria	Streator	Pontiac	Grand Total
1999	1968	Sum of Retired Cost				114.78			114.78
		Sum of Removal Cost				260.86			260.86
	1970	Sum of Original Quantity				1.00			1.00
		Sum of Retired Cost				285.81			285.81
		Sum of Removal Cost				343.00			343.00
	1972	Sum of Original Quantity				2.00			2.00
		Sum of Retired Cost				553.10			553.10
		Sum of Removal Cost				830.42			830.42
	1973	Sum of Original Quantity			1.00	1.00			2.00
		Sum of Retired Cost			328.59	156.81			485.40
		Sum of Removal Cost			310.78	134.96			445.74
	1974	Sum of Original Quantity				2.00			2.00
		Sum of Retired Cost				1,304.45			1,304.45
		Sum of Removal Cost				796.89			796.89
	1975	Sum of Original Quantity			1.00				1.00
		Sum of Retired Cost			328.11				328.11
		Sum of Removal Cost			315.49				315.49
	1976	Sum of Original Quantity				1.00			1.00
		Sum of Retired Cost				394.85			394.85
		Sum of Removal Cost				337.46			337.46
	1978	Sum of Original Quantity			1.00	1.00			2.00
		Sum of Retired Cost			252.31	352.76			605.07
		Sum of Removal Cost			159.32	303.60			462.92
	1979	Sum of Original Quantity				2.00			2.00
		Sum of Retired Cost				943.07			943.07
		Sum of Removal Cost				1,904.39			1,904.39
	1980	Sum of Original Quantity				1.00			1.00
		Sum of Retired Cost				344.86			344.86
		Sum of Removal Cost				403.42			403.42
	1981	Sum of Original Quantity				1.00			1.00
		Sum of Retired Cost				417.71			417.71
		Sum of Removal Cost				337.41			337.41
	1982	Sum of Original Quantity			1.00	1.00			2.00
		Sum of Retired Cost			317.79	438.46			756.25
		Sum of Removal Cost			226.41	459.23			685.64
	1983	Sum of Original Quantity		1.00					1.00
		Sum of Retired Cost		689.60					689.60
		Sum of Removal Cost		1,056.16					1,056.16
	1984	Sum of Original Quantity				1.00			1.00
		Sum of Retired Cost				923.22			923.22
		Sum of Removal Cost				794.57			794.57
	1985	Sum of Original Quantity			1.00	2.00			3.00
		Sum of Retired Cost			324.78	1,636.27			1,961.05
		Sum of Removal Cost			290.86	7,866.84			8,157.70
	1987	Sum of Original Quantity			1.00				1.00
		Sum of Retired Cost			366.24				366.24
		Sum of Removal Cost			163.02				163.02
	1988	Sum of Original Quantity				2.00			2.00
		Sum of Retired Cost				2,014.24			2,014.24
		Sum of Removal Cost				1,733.56			1,733.56
	1989	Sum of Original Quantity			1.00	1.00			2.00
		Sum of Retired Cost			357.64	894.36			1,252.00

Asset Type	(All)

Exhibit 2.7
Replacement Hydrants

Fiscal Year	Year In Se	Data	Responsible BU						Grand Total
			Cairo	Alton	Interurban	Eagle	Strearor	Pontiac	
1999	1989	Sum of Removal Cost			321.57	228.32			549.89
	1990	Sum of Original Quantity				1.00			1.00
		Sum of Retired Cost				527.61			527.61
		Sum of Removal Cost				454.09			454.09
	1992	Sum of Original Quantity			1.00	2.00			3.00
		Sum of Retired Cost			434.97	1,093.27			1,528.24
		Sum of Removal Cost			418.23	940.93			1,359.16
	1994	Sum of Original Quantity			2.00				2.00
		Sum of Retired Cost			763.21				763.21
		Sum of Removal Cost			1,583.20				1,583.20
	1995	Sum of Original Quantity				1.00			1.00
		Sum of Retired Cost				560.48			560.48
		Sum of Removal Cost				482.38			482.38
	1996	Sum of Original Quantity			1.00	3.00			4.00
		Sum of Retired Cost			355.48	2,035.59			2,391.07
		Sum of Removal Cost			155.26	1,991.03			2,146.29
	1997	Sum of Original Quantity				3.00			3.00
		Sum of Retired Cost				2,324.64			2,324.64
		Sum of Removal Cost				2,008.54			2,008.54
	1998	Sum of Original Quantity		1.00		1.00			2.00
		Sum of Retired Cost		855.52		635.72			1,491.24
		Sum of Removal Cost		1,310.28		348.28			1,658.56
1999 Sum of Original Quantity			2.00	29.00	16.00	93.00			140.00
1999 Sum of Retired Cost			77.20	2,260.60	4,373.15	21,530.81			28,241.76
1999 Sum of Removal Cost			191.83	8,919.13	4,908.40	54,769.65			68,789.01
In 2000	1924	Sum of Original Quantity				1.00			1.00
		Sum of Retired Cost				5.63			5.63
		Sum of Removal Cost				4.85			4.85
	1936	Sum of Original Quantity	4.00			20.00			24.00
		Sum of Retired Cost	78.35			471.90			550.25
		Sum of Removal Cost	1,721.98			9,058.94			10,780.92
	1938	Sum of Original Quantity		1.00					1.00
		Sum of Retired Cost		10.08					10.08
		Sum of Removal Cost		15.44					15.44
	1940	Sum of Original Quantity	1.00						1.00
		Sum of Retired Cost	28.73						28.73
		Sum of Removal Cost	1,538.52						1,538.52
	1942	Sum of Original Quantity		4.00					4.00
		Sum of Retired Cost		292.27					292.27
		Sum of Removal Cost		1,099.58					1,099.58
	1943	Sum of Original Quantity		1.00					1.00
		Sum of Retired Cost		62.82					62.82
		Sum of Removal Cost		249.03					249.03
	1946	Sum of Original Quantity		1.00					1.00
		Sum of Retired Cost		84.84					84.84
		Sum of Removal Cost		244.24					244.24
	1947	Sum of Original Quantity		5.00					5.00
		Sum of Retired Cost		357.72					357.72
		Sum of Removal Cost		1,012.98					1,012.98
	1948	Sum of Original Quantity			4.00				4.00
		Sum of Retired Cost			284.76				284.76
		Sum of Removal Cost			1,287.93				1,287.93

Asset Type	(All)

Exhibit 2.7
Replacement Hydrants

			Responsible BU						
Fiscal Year	Year In Se	Data	Cairo	Alton	Interurban	Peoria	Streator	Pontiac	Grand Total
2000	1949	Sum of Original Quantity			5.00				5.00
		Sum of Retired Cost			537.17				537.17
		Sum of Removal Cost			659.80				659.80
	1950	Sum of Original Quantity				2.00			2.00
		Sum of Retired Cost				220.81			220.81
		Sum of Removal Cost				775.82			775.82
	1951	Sum of Original Quantity				1.00	1.00		2.00
		Sum of Retired Cost				115.87	190.53		306.40
		Sum of Removal Cost				343.35	527.94		871.29
	1953	Sum of Original Quantity		1.00	1.00	1.00			3.00
		Sum of Retired Cost		107.01	73.80	406.48			587.29
		Sum of Removal Cost		158.02	443.56	743.43			1,345.01
	1954	Sum of Original Quantity	1.00		3.00		1.00		5.00
		Sum of Retired Cost	85.02		544.38		87.23		716.63
		Sum of Removal Cost	247.80		342.35		896.99		1,487.14
	1955	Sum of Original Quantity			2.00				2.00
		Sum of Retired Cost			145.63				145.63
		Sum of Removal Cost			399.29				399.29
	1956	Sum of Original Quantity	1.00		1.00				2.00
		Sum of Retired Cost	86.22		94.24				180.46
		Sum of Removal Cost	123.39		76.76				200.15
	1957	Sum of Original Quantity		1.00	1.00		1.00		3.00
		Sum of Retired Cost		182.51	52.02		305.01		539.54
		Sum of Removal Cost		237.37	42.37		331.32		611.06
	1958	Sum of Original Quantity				2.00			2.00
		Sum of Retired Cost				439.72			439.72
		Sum of Removal Cost				616.99			616.99
	1961	Sum of Original Quantity			1.00				1.00
		Sum of Retired Cost			92.61				92.61
		Sum of Removal Cost			213.02				213.02
	1962	Sum of Original Quantity				1.00		1.00	2.00
		Sum of Retired Cost				285.99		219.86	505.85
		Sum of Removal Cost				523.08			523.08
	1965	Sum of Original Quantity			1.00	1.00			2.00
		Sum of Retired Cost			109.18	149.90			259.08
		Sum of Removal Cost			104.98	274.17			379.15
	1969	Sum of Original Quantity				2.00			2.00
		Sum of Retired Cost				691.92			691.92
		Sum of Removal Cost				(48.48)			(48.48)
	1971	Sum of Original Quantity			1.00	2.00			3.00
		Sum of Retired Cost			152.66	461.16			613.82
		Sum of Removal Cost			54.47	366.36			420.83
	1972	Sum of Original Quantity				1.00			1.00
		Sum of Retired Cost				254.39			254.39
		Sum of Removal Cost				465.28			465.28
	1973	Sum of Original Quantity				3.00			3.00
		Sum of Retired Cost				484.21			484.21
		Sum of Removal Cost				1,254.19			1,254.19
	1974	Sum of Original Quantity				3.00	1.00		4.00
		Sum of Retired Cost				1,590.26	417.78		2,008.04
		Sum of Removal Cost				1,718.41	453.81		2,172.22
	1976	Sum of Original Quantity			2.00	3.00			5.00

Asset Type	(All)

Exhibit 2.7
Replacement Hydrants

			Responsible BU						
Fiscal Year	Year In Se	Data	Cairo	Alton	Interurban	Peoria	Streator	Pontiac	Grand Total
2000	1976	Sum of Retired Cost			940.41	1,625.94			2,566.35
		Sum of Removal Cost			672.72	2,102.80			2,775.52
	1977	Sum of Original Quantity				2.00			2.00
		Sum of Retired Cost				1,659.73			1,659.73
		Sum of Removal Cost				1,395.64			1,395.64
	1978	Sum of Original Quantity		1.00		4.00			5.00
		Sum of Retired Cost		367.02		1,735.66			2,102.68
		Sum of Removal Cost		164.08		2,133.75			2,297.83
	1980	Sum of Original Quantity			2.00	1.00			3.00
		Sum of Retired Cost			573.78	384.24			958.02
		Sum of Removal Cost			313.62	702.79			1,016.41
	1984	Sum of Original Quantity			2.00	1.00			3.00
		Sum of Retired Cost			902.24	439.66			1,341.90
		Sum of Removal Cost			572.78	(422.15)			150.63
	1985	Sum of Original Quantity			1.00				1.00
		Sum of Retired Cost			297.20				297.20
		Sum of Removal Cost			242.07				242.07
	1986	Sum of Original Quantity				2.00			2.00
		Sum of Retired Cost				1,310.76			1,310.76
		Sum of Removal Cost				1,535.23			1,535.23
	1987	Sum of Original Quantity	1.00						1.00
		Sum of Retired Cost	452.33						452.33
		Sum of Removal Cost	268.44						268.44
	1988	Sum of Original Quantity				1.00			1.00
		Sum of Retired Cost				402.32			402.32
		Sum of Removal Cost				319.74			319.74
	1990	Sum of Original Quantity	1.00						1.00
		Sum of Retired Cost	344.90						344.90
		Sum of Removal Cost							
	1992	Sum of Original Quantity				2.00			2.00
		Sum of Retired Cost				1,418.02			1,418.02
		Sum of Removal Cost				1,663.88			1,663.88
	1993	Sum of Original Quantity				1.00			1.00
		Sum of Retired Cost				963.87			963.87
		Sum of Removal Cost				829.56			829.56
	1994	Sum of Original Quantity				1.00			1.00
		Sum of Retired Cost				471.95			471.95
		Sum of Removal Cost				863.21			863.21
	1997	Sum of Original Quantity				1.00			1.00
		Sum of Retired Cost				528.93			528.93
		Sum of Removal Cost				455.23			455.23
	1998	Sum of Original Quantity			1.00	2.00			3.00
		Sum of Retired Cost			459.47	1,224.78			1,684.25
		Sum of Removal Cost			330.15	1,054.11			1,384.26
	(blank)	Sum of Original Quantity				1.00			1.00
		Sum of Retired Cost				2,736.03			2,736.03
		Sum of Removal Cost				108.00			108.00
2000 Sum of Original Quantity			9.00	15.00	28.00	62.00	4.00	1.00	119.00
2000 Sum of Retired Cost			1,075.55	1,464.27	5,259.55	20,480.13	1,000.55	219.86	29,499.91
2000 Sum of Removal Cost			3,900.13	3,180.74	5,755.86	28,838.17	2,210.06		43,884.96
2001	1924	Sum of Original Quantity			1.00	2.00			3.00
		Sum of Retired Cost			27.90	60.02			87.92

Asset Type	(All)

Exhibit 2.7
Replacement Hydrants

			Responsible BU					
Fiscal Year	Year In Se	Data	Cairo	Alton	Interurban	Peoria	Streator	Grand Total
2001	1924	Sum of Removal Cost			175.68	186.44		362.12
	1936	Sum of Original Quantity				2.00		2.00
		Sum of Retired Cost				57.26		57.26
		Sum of Removal Cost				586.36		586.36
	1938	Sum of Original Quantity		1.00		1.00		2.00
		Sum of Retired Cost		9.14		27.58		36.72
		Sum of Removal Cost		90.09		23.74		113.83
	1947	Sum of Original Quantity		1.00				1.00
		Sum of Retired Cost		66.77				66.77
		Sum of Removal Cost		1,392.15				1,392.15
	1948	Sum of Original Quantity			1.00			1.00
		Sum of Retired Cost			55.48			55.48
		Sum of Removal Cost			248.11			248.11
	1951	Sum of Original Quantity			2.00			2.00
		Sum of Retired Cost			112.37			112.37
		Sum of Removal Cost			1,394.18			1,394.18
	1952	Sum of Original Quantity			1.00			1.00
		Sum of Retired Cost			84.88			84.88
		Sum of Removal Cost			104.84			104.84
	1954	Sum of Original Quantity				10.00		10.00
		Sum of Retired Cost				329.40		329.40
		Sum of Removal Cost				3,306.13		3,306.13
	1955	Sum of Original Quantity			1.00			1.00
		Sum of Retired Cost			80.30			80.30
		Sum of Removal Cost			116.71			116.71
	1957	Sum of Original Quantity				1.00		1.00
		Sum of Retired Cost				84.01		84.01
		Sum of Removal Cost				162.28		162.28
	1958	Sum of Original Quantity			1.00	1.00		2.00
		Sum of Retired Cost			108.03	250.16		358.19
		Sum of Removal Cost			1,385.09	215.30		1,600.39
	1959	Sum of Original Quantity				1.00		1.00
		Sum of Retired Cost				109.70		109.70
		Sum of Removal Cost				94.41		94.41
	1961	Sum of Original Quantity				2.00		2.00
		Sum of Retired Cost				351.48		351.48
		Sum of Removal Cost				1,070.92		1,070.92
	1962	Sum of Original Quantity				1.00		1.00
		Sum of Retired Cost				137.68		137.68
		Sum of Removal Cost				250.53		250.53
	1963	Sum of Original Quantity			1.00			1.00
		Sum of Retired Cost			70.48			70.48
		Sum of Removal Cost			903.64			903.64
	1964	Sum of Original Quantity			2.00	2.00		4.00
		Sum of Retired Cost			184.02	183.71		367.73
		Sum of Removal Cost			465.14	1,231.47		1,696.61
	1965	Sum of Original Quantity		2.00		1.00		3.00
		Sum of Retired Cost		183.74		145.23		328.97
		Sum of Removal Cost		216.69		140.08		356.77
	1967	Sum of Original Quantity				2.00		2.00
		Sum of Retired Cost				212.86		212.86
		Sum of Removal Cost				534.11		534.11

Asset Type	(All)

Exhibit 2.7
Replacement Hydrants

Fiscal Year	Year In Se	Data	Responsible BU						
			Cairo	Alton	Interurban	Peoria	Streator	Pontiac	Grand Total
2001	1968	Sum of Original Quantity				3.00			3.00
		Sum of Retired Cost				790.07			790.07
		Sum of Removal Cost				267.37			267.37
	1969	Sum of Original Quantity				2.00			2.00
		Sum of Retired Cost				682.20			682.20
		Sum of Removal Cost				1,156.23			1,156.23
	1971	Sum of Original Quantity		2.00					2.00
		Sum of Retired Cost		231.07					231.07
		Sum of Removal Cost		997.34					997.34
	1972	Sum of Original Quantity				1.00			1.00
		Sum of Retired Cost				240.37			240.37
		Sum of Removal Cost				206.88			206.88
	1973	Sum of Original Quantity		1.00					1.00
		Sum of Retired Cost		226.10					226.10
		Sum of Removal Cost		217.40					217.40
	1974	Sum of Original Quantity				2.00			2.00
		Sum of Retired Cost				1,632.56			1,632.56
		Sum of Removal Cost				1,738.56			1,738.56
	1976	Sum of Original Quantity				6.00			6.00
		Sum of Retired Cost				2,584.12			2,584.12
		Sum of Removal Cost				4,099.01			4,099.01
	1977	Sum of Original Quantity				1.00			1.00
		Sum of Retired Cost				409.81			409.81
		Sum of Removal Cost				745.68			745.68
	1978	Sum of Original Quantity		1.00					1.00
		Sum of Retired Cost		331.77					331.77
		Sum of Removal Cost		319.00					319.00
	1979	Sum of Original Quantity				3.00			3.00
		Sum of Retired Cost				1,058.78			1,058.78
		Sum of Removal Cost				1,208.11			1,208.11
	1981	Sum of Original Quantity		1.00		1.00			2.00
		Sum of Retired Cost		280.02		433.56			713.58
		Sum of Removal Cost		345.83		490.28			836.11
	1982	Sum of Original Quantity		1.00		2.00			3.00
		Sum of Retired Cost		262.25		788.21			1,050.46
		Sum of Removal Cost		381.18		1,618.12			1,999.30
	1983	Sum of Original Quantity		1.00					1.00
		Sum of Retired Cost		246.38					246.38
		Sum of Removal Cost		236.90					236.90
	1984	Sum of Original Quantity				1.00			1.00
		Sum of Retired Cost				396.06			396.06
		Sum of Removal Cost				1,027.60			1,027.60
	1986	Sum of Original Quantity		1.00		2.00			3.00
		Sum of Retired Cost		243.55		809.59			1,053.14
		Sum of Removal Cost		1,745.77		2,235.34			3,981.11
	1988	Sum of Original Quantity		1.00		2.00			3.00
		Sum of Retired Cost		489.11		762.93			1,252.04
		Sum of Removal Cost		470.29		1,652.89			2,123.18
	1991	Sum of Original Quantity				1.00			1.00
		Sum of Retired Cost				368.42			368.42
		Sum of Removal Cost				711.64			711.64
	1992	Sum of Original Quantity				2.00			2.00

Asset Type	(All)

Exhibit 2.7
Replacement Hydrants

Fiscal Year	Year In Se	Data	Responsible BU						
			Cairo	Alton	Interurban	Peoria	Streator	Pontiac	Grand Total
2001	1992	Sum of Retired Cost				1,330.16			1,330.16
		Sum of Removal Cost				1,102.28			1,102.28
	1993	Sum of Original Quantity			1.00				1.00
		Sum of Retired Cost			285.38				285.38
		Sum of Removal Cost			274.40				274.40
	1996	Sum of Original Quantity			1.00				1.00
		Sum of Retired Cost			506.04				506.04
		Sum of Removal Cost			486.57				486.57
	1997	Sum of Original Quantity				1.00			1.00
		Sum of Retired Cost				496.63			496.63
		Sum of Removal Cost				959.27			959.27
	1998	Sum of Original Quantity				1.00			1.00
		Sum of Retired Cost				552.58			552.58
		Sum of Removal Cost				475.58			475.58
	2000	Sum of Original Quantity				1.00			1.00
		Sum of Retired Cost				1,260.06			1,260.06
		Sum of Removal Cost				1,084.48			1,084.48
2001 Sum of Original Quantity			2.00	2.00	21.00	58.00			83.00
2001 Sum of Retired Cost			183.74	75.91	3,825.13	16,545.20			20,629.98
2001 Sum of Removal Cost			216.69	1,482.24	10,268.07	28,581.09			40,548.09
2002	1898	Sum of Original Quantity				1.00			1.00
		Sum of Retired Cost				66.13			66.13
		Sum of Removal Cost				56.92			56.92
	1909	Sum of Original Quantity			1.00				1.00
		Sum of Retired Cost			12.22				12.22
		Sum of Removal Cost			11.75				11.75
	1924	Sum of Original Quantity				6.00			6.00
		Sum of Retired Cost				7.92			7.92
		Sum of Removal Cost				6.82			6.82
	1938	Sum of Original Quantity				1.00			1.00
		Sum of Retired Cost				11.68			11.68
		Sum of Removal Cost				10.05			10.05
	1940	Sum of Original Quantity	2.00						2.00
		Sum of Retired Cost	93.32						93.32
		Sum of Removal Cost	289.72						289.72
	1947	Sum of Original Quantity						1.00	1.00
		Sum of Retired Cost						80.20	80.20
		Sum of Removal Cost						20.40	20.40
	1948	Sum of Original Quantity				1.00			1.00
		Sum of Retired Cost				47.21			47.21
		Sum of Removal Cost				40.63			40.63
	1949	Sum of Original Quantity				1.00			1.00
		Sum of Retired Cost				52.11			52.11
		Sum of Removal Cost				44.85			44.85
	1951	Sum of Original Quantity		2.00					2.00
		Sum of Retired Cost		292.78					292.78
		Sum of Removal Cost		224.20					224.20
	1952	Sum of Original Quantity			1.00				1.00
		Sum of Retired Cost			187.88				187.88
		Sum of Removal Cost			180.65				180.65
	1953	Sum of Original Quantity			4.00		1.00		5.00
		Sum of Retired Cost			791.60		123.07		914.67

Asset Type	(All)

Exhibit 2.7
Replacement Hydrants

Fiscal Year	Year In Se	Data	Responsible BU Alton	Interurban	Peoria	Streator	Pontiac	Grand Total
2002	1953	Sum of Removal Cost		761.14		484.28		1,245.42
	1954	Sum of Original Quantity	4.00					4.00
		Sum of Retired Cost	873.68					873.68
		Sum of Removal Cost	669.05					669.05
	1955	Sum of Original Quantity	4.00	2.00				6.00
		Sum of Retired Cost	350.84	291.56				642.40
		Sum of Removal Cost	268.67	280.34				549.01
	1956	Sum of Original Quantity	1.00	2.00		1.00		4.00
		Sum of Retired Cost	82.49	416.60		168.28		667.37
		Sum of Removal Cost	126.34	400.57		662.18		1,189.09
	1958	Sum of Original Quantity		2.00		1.00		3.00
		Sum of Retired Cost		594.12		246.09		840.21
		Sum of Removal Cost		571.26		968.36		1,539.62
	1959	Sum of Original Quantity			3.00			3.00
		Sum of Retired Cost			483.02			483.02
		Sum of Removal Cost			415.71			415.71
	1961	Sum of Original Quantity			1.00			1.00
		Sum of Retired Cost			37.44			37.44
		Sum of Removal Cost			32.22			32.22
	1962	Sum of Original Quantity			1.00			1.00
		Sum of Retired Cost			40.04			40.04
		Sum of Removal Cost			34.46			34.46
	1963	Sum of Original Quantity			1.00			1.00
		Sum of Retired Cost			94.38			94.38
		Sum of Removal Cost			81.23			81.23
	1964	Sum of Original Quantity		1.00				1.00
		Sum of Retired Cost		268.41				268.41
		Sum of Removal Cost		258.08				258.08
	1965	Sum of Original Quantity			1.00			1.00
		Sum of Retired Cost			111.57			111.57
		Sum of Removal Cost			96.02			96.02
	1966	Sum of Original Quantity	2.00	1.00	9.00			12.00
		Sum of Retired Cost	387.70	199.23	1,955.44			2,542.37
		Sum of Removal Cost	296.89	191.56	1,682.96			2,171.42
	1968	Sum of Original Quantity		2.00				2.00
		Sum of Retired Cost		447.50				447.50
		Sum of Removal Cost		430.28				430.28
	1969	Sum of Original Quantity			1.00			1.00
		Sum of Retired Cost			617.25			617.25
		Sum of Removal Cost			(2,620.01)			(2,620.01)
	1970	Sum of Original Quantity			1.00			1.00
		Sum of Retired Cost			54.02			54.02
		Sum of Removal Cost			46.49			46.49
	1971	Sum of Original Quantity			2.00			2.00
		Sum of Retired Cost			113.86			113.86
		Sum of Removal Cost			97.99			97.99
	1972	Sum of Original Quantity			2.00			2.00
		Sum of Retired Cost			651.62			651.62
		Sum of Removal Cost			560.82			560.82
	1973	Sum of Original Quantity			3.00			3.00
		Sum of Retired Cost			1,118.65			1,118.65
		Sum of Removal Cost			962.77			962.77

Asset Type	(All)

Exhibit 2.7
Replacement Hydrants

			Responsible BU						
Fiscal Year	Year In Se	Data	Cairo	Alton	Interurban	Peoria	Streator	Pontiac	Grand Total
2002	1976	Sum of Original Quantity				1.00			1.00
		Sum of Retired Cost				106.18			106.18
		Sum of Removal Cost				91.38			91.38
	1977	Sum of Original Quantity				2.00			2.00
		Sum of Retired Cost				1,471.20			1,471.20
		Sum of Removal Cost				1,266.19			1,266.19
	1978	Sum of Original Quantity			1.00				1.00
		Sum of Retired Cost			494.12				494.12
		Sum of Removal Cost			475.11				475.11
	1979	Sum of Original Quantity			2.00	1.00			3.00
		Sum of Retired Cost			732.60	1,161.25			1,893.85
		Sum of Removal Cost			704.41	999.44			1,703.85
	1980	Sum of Original Quantity						1.00	1.00
		Sum of Retired Cost						327.52	327.52
		Sum of Removal Cost						83.32	83.32
	1981	Sum of Original Quantity				3.00			3.00
		Sum of Retired Cost				1,444.73			1,444.73
		Sum of Removal Cost				1,243.41			1,243.41
	1982	Sum of Original Quantity				2.00			2.00
		Sum of Retired Cost				1,301.68			1,301.68
		Sum of Removal Cost				1,120.30			1,120.30
	1983	Sum of Original Quantity	2.00		1.00				3.00
		Sum of Retired Cost	663.54		628.58				1,292.12
		Sum of Removal Cost			604.39				604.39
	1984	Sum of Original Quantity			1.00	5.00			6.00
		Sum of Retired Cost			579.04	2,459.73			3,038.77
		Sum of Removal Cost			556.76	2,258.68			2,815.44
	1987	Sum of Original Quantity						1.00	1.00
		Sum of Retired Cost						720.12	720.12
		Sum of Removal Cost						183.20	183.20
	1988	Sum of Original Quantity				2.00			2.00
		Sum of Retired Cost				939.40			939.40
		Sum of Removal Cost				808.50			808.50
	1990	Sum of Original Quantity				1.00			1.00
		Sum of Retired Cost				351.43			351.43
		Sum of Removal Cost				302.46			302.46
	1991	Sum of Original Quantity				5.00			5.00
		Sum of Retired Cost				4,221.25			4,221.25
		Sum of Removal Cost				1,207.42			1,207.42
	1996	Sum of Original Quantity				4.00			4.00
		Sum of Retired Cost				2,252.74			2,252.74
		Sum of Removal Cost				2,558.61			2,558.61
	1998	Sum of Original Quantity			5.00				5.00
		Sum of Retired Cost			3,743.75				3,743.75
		Sum of Removal Cost			3,599.70				3,599.70
	2001	Sum of Original Quantity			1.00				1.00
		Sum of Retired Cost			1,208.11				1,208.11
		Sum of Removal Cost			1,161.62				1,161.62
2002 Sum of Original Quantity			4.00	13.00	27.00	61.00	3.00	3.00	111.00
2002 Sum of Retired Cost			756.86	1,987.49	10,595.32	21,171.93	537.44	1,127.84	36,176.88
2002 Sum of Removal Cost			289.72	1,585.15	10,187.63	13,406.34	2,114.83	286.93	27,870.59
2003	1924	Sum of Original Quantity				2.00			2.00

Asset Type	(All)

Exhibit 2.7
Replacement Hydrants

Fiscal Year	Year In Se	Data	Responsible BU						Grand Total
			Cairo	Alton	Interurban	Peoria	Streator	Pontiac	
2003	1924	Sum of Retired Cost					2.08		2.08
		Sum of Removal Cost					1.79		1.79
	1949	Sum of Original Quantity					1.00		1.00
		Sum of Retired Cost					52.11		52.11
		Sum of Removal Cost					44.85		44.85
	1950	Sum of Original Quantity			1.00				1.00
		Sum of Retired Cost			7.71				7.71
		Sum of Removal Cost			7.41				7.41
	1951	Sum of Original Quantity		1.00					1.00
		Sum of Retired Cost		(146.39)					(146.39)
		Sum of Removal Cost							
	1953	Sum of Original Quantity	2.00		1.00				3.00
		Sum of Retired Cost	261.98		11.82				273.80
		Sum of Removal Cost	94.04		11.37				105.41
	1954	Sum of Original Quantity		2.00	1.00				3.00
		Sum of Retired Cost		(436.84)	13.68				(423.16)
		Sum of Removal Cost			13.15				13.15
	1955	Sum of Original Quantity	1.00	2.00	1.00				4.00
		Sum of Retired Cost	129.15	(175.42)	8.41				(37.86)
		Sum of Removal Cost	46.36		8.09				54.45
	1956	Sum of Original Quantity	1.00		3.00				4.00
		Sum of Retired Cost	133.70		264.60				398.30
		Sum of Removal Cost	47.99		254.42				302.41
	1957	Sum of Original Quantity			1.00				1.00
		Sum of Retired Cost			15.81				15.81
		Sum of Removal Cost			15.20				15.20
	1960	Sum of Original Quantity					2.00		2.00
		Sum of Retired Cost					419.58		419.58
		Sum of Removal Cost					361.11		361.11
	1961	Sum of Original Quantity		2.00					2.00
		Sum of Retired Cost		402.52					402.52
		Sum of Removal Cost		616.48					616.48
	1962	Sum of Original Quantity			1.00				1.00
		Sum of Retired Cost			14.75				14.75
		Sum of Removal Cost			14.18				14.18
	1963	Sum of Original Quantity		1.00					1.00
		Sum of Retired Cost		201.00					201.00
		Sum of Removal Cost		307.84					307.84
	1964	Sum of Original Quantity			1.00				1.00
		Sum of Retired Cost			9.82				9.82
		Sum of Removal Cost			9.44				9.44
	1966	Sum of Original Quantity		1.00				1.00	2.00
		Sum of Retired Cost		(193.85)				166.47	(27.38)
		Sum of Removal Cost							
	1967	Sum of Original Quantity		1.00					1.00
		Sum of Retired Cost		190.09					190.09
		Sum of Removal Cost		291.13					291.13
	1968	Sum of Original Quantity			1.00				1.00
		Sum of Retired Cost			18.69				18.69
		Sum of Removal Cost			17.97				17.97
	1970	Sum of Original Quantity			1.00	1.00			2.00
		Sum of Retired Cost			21.67	173.78			195.45

Asset Type	(All)

Exhibit 2.7
Replacement Hydrants

			Responsible BU					
Fiscal Year	Year In Se	Data	Cairo	Alton	Interurban	Peoria	Streator	Pontiac	Grand Totals
2003	1970	Sum of Removal Cost			20.84	149.56			170.40
	1971	Sum of Original Quantity			3.00	5.00			8.00
		Sum of Retired Cost			416.26	657.80			1,074.06
		Sum of Removal Cost			400.24	566.14			966.38
	1972	Sum of Original Quantity			1.00	1.00			2.00
		Sum of Retired Cost			18.40	65.70			84.10
		Sum of Removal Cost			17.69	56.55			74.24
	1973	Sum of Original Quantity				6.00			6.00
		Sum of Retired Cost				598.16			598.16
		Sum of Removal Cost				514.81			514.81
	1974	Sum of Original Quantity			1.00				1.00
		Sum of Retired Cost			23.37				23.37
		Sum of Removal Cost			22.47				22.47
	1975	Sum of Original Quantity				1.00			1.00
		Sum of Retired Cost				79.93			79.93
		Sum of Removal Cost				68.79			68.79
	1977	Sum of Original Quantity				1.00			1.00
		Sum of Retired Cost				133.72			133.72
		Sum of Removal Cost				115.09			115.09
	1978	Sum of Original Quantity		1.00					1.00
		Sum of Retired Cost		636.22					636.22
		Sum of Removal Cost		974.41					974.41
	1980	Sum of Original Quantity			1.00				1.00
		Sum of Retired Cost			50.38				50.38
		Sum of Removal Cost			48.44				48.44
	1981	Sum of Original Quantity				2.00			2.00
		Sum of Retired Cost				1,328.18			1,328.18
		Sum of Removal Cost				1,143.10			1,143.10
	1982	Sum of Original Quantity			1.00	1.00			2.00
		Sum of Retired Cost			42.96	408.92			451.88
		Sum of Removal Cost			41.31	351.94			393.25
	1983	Sum of Original Quantity	1.00		2.00				3.00
		Sum of Retired Cost	(663.54)		98.06				(565.48)
		Sum of Removal Cost			94.29				94.29
	1984	Sum of Original Quantity			2.00	6.00			8.00
		Sum of Retired Cost			46.24	1,476.86			1,523.10
		Sum of Removal Cost			44.46	1,271.07			1,315.53
	1987	Sum of Original Quantity			1.00				1.00
		Sum of Retired Cost			26.25				26.25
		Sum of Removal Cost			25.24				25.24
	1988	Sum of Original Quantity				1.00			1.00
		Sum of Retired Cost				351.80			351.80
		Sum of Removal Cost				302.78			302.78
	1989	Sum of Original Quantity			2.00				2.00
		Sum of Retired Cost			737.58				737.58
		Sum of Removal Cost			709.20				709.20
	1991	Sum of Original Quantity				1.00			1.00
		Sum of Retired Cost				347.60			347.60
		Sum of Removal Cost				299.16			299.16
	1992	Sum of Original Quantity				1.00			1.00
		Sum of Retired Cost				131.46			131.46
		Sum of Removal Cost				113.14			113.14