Residence 5. The other residence on the south side of 125E is shown on image #6 and is 264 feet south of the line (PDM Cross Ex. 1). MCPO noted both of these residences 4 and 5, but Staff noted neither of them, even though they are clearly visible and clearly within Mr. Rockrohr's definition of "close proximity."

Residence 6. The other two residences are on CR 125E on the north side of the route. One is shown on PDM Cross Ex. 1, image #15, located 530 feet from the MCPO route centerline.

Residence 7. The other residence is shown on PDM Cross Ex. 1, image #16, located 525 feet from the MCPO route centerline. It appears that MCPO identified one but not both of these residences, and Staff identified neither.

Residence 8. This residence is located further to the east in Garrett Twp. Section 4, also shown on MCPO Corrected Ex. 2.2, p.9. On the west side of CR 250E, south of the MCPO route, right in the middle of Section 4, is a residence shown on MCPO Cross Ex. 1, image #7. This residence is 497 feet from the MCPO route centerline, but was not identified by MCPO or Staff.

Residence 9. The next residence is located one section to the east in Garrett Twp. Section 3, just north of the MCPO route, and is the property underneath the words "driveway" shown on the right center of MCPO Corrected Ex. 2.2, p.9. A close-up of this residence is shown on MCPO Cross Ex. 1, image #8. This residence is located 260 feet north of the MCPO route centerline, and was identified by MCPO, but missed by Staff.

Residence 10. The next residence is located in Tuscola Township, Section 2, as shown on MCPO Corrected Ex. 2.2, p.11. The residence is located just south of the MCPO route and is visible on the far right center of MCPO Corrected Ex. 2.2, p.11. This residence is shown on MCPO Cross Ex. 1, image #9 and is located 464 feet south of the MCPO route centerline. This residence was located by MCPO, but not by Staff.