Illinois Commerce Commission

Pipeline Safety

Exit Meeting Documentation Form

Operator:	CENTER ETHANOL COMPANY, LLC
Inspection Unit(s):	CENTER ETHANOL COMPANY - Sauget
Date of Meeting:	11/08/2012
Pipeline Safety Analyst:	Matt Smith
Exit Meeting Contact:	Denny Crown

Issues Identified/Amendments/Probable Violations:

ISSUE(S) FOUND:

NO ISSUES FOUND.

ISSUE(S) CORRECTED:

2012-S1-00076 - The plastic pipe that was located on the inlet and outlet of the relief device configuration have been replaced with steel pipe. The steel pipe is considered the support needed for the relief device.

NOTICE OF AMENDMENT(S) FOUND:

NO NOAs FOUND.

NOA(S) CORRECTED:

NO NOAs CORRECTED.

NOTICE OF PROBABLE VIOLATION(S) FOUND:

NO NOPVs FOUND.

NOPV(S) CORRECTED:

2012-V1-00060 - Staff observed that the plastic pipe that was located above ground at the relief device and at the take point has been removed and replaced with steel pipe that has a protective coating applied.

2012-V1-00061 - The plastic pipe that was attached to the steel piping and relief device configuration has been removed with steel pipe. The newly installed steel pipe is able to support the weight of the relief device, above ground steel pipe, and associated valves.

2012-V1-00063 - USDI forwarded a copy of the OQ records for USDI personnel that anticipate conducting activities on the Center Ethanol pipeline. The records indicated that the USDI personnel were operator qualified.

Pipeline Safety Analyst Signature: Matt Smith

Operator Representative Signature: Denny Crown