

STATE OF ILLINOIS



ILLINOIS COMMERCE COMMISSION
TRANSPORTATION DIVISION / RAIL SAFETY SECTION

Michael E. Stead

Rail Safety Program Administrator

April 23, 2008

Michael A. Flynn
Assistant Village Administrator
Village of Mundelein
440 E. Hawley Street
Mundelein, IL 60060

Dear Mr. Flynn:

This is in response to your letter dated April 17, 2008, with which you indicated that the Village of Mundelein had removed the automatic wayside horn system (AHS) from the Peterson Road (**AAR/DOT #689710T, railroad milepost 42.38**) and the Winchester Road (**AAR/DOT #689709Y, railroad milepost 41.78**) highway-rail grade crossings of the Canadian National's (CN) track. You had also requested guidance from this office on what to do with the AHS materials.

This office has no objection to the Village of Mundelein utilizing the AHS materials removed from the Peterson Road and Winchester Road crossings as replacement parts for the existing active wayside horn systems that remain in place.

I trust this information will be helpful. If you have any questions, please contact Rod Bergeron, Senior Railroad Safety Specialist, at (217) 557-1287 or rbergero@icc.illinois.gov.

Very truly yours,

A handwritten signature in black ink, appearing to read "Michael E. Stead".

Michael E. Stead
Rail Safety Program Administrator

cc: John Henriksen, CN
RLB