

OFFICIAL FILE

I.C.C. DOCKET NO. 12-0183

ComEd Exhibit No. 3

Witness John Valdez

Date 11-15-12 Reporter Sylvia Franklin

Buechler, Erin M:(ComEd)

From: Valdez, John J. Jr.(ComEd)
Sent: Friday, November 02, 2012 2:26 PM
To: Buechler, Erin M:(ComEd)
Subject: Outage Tkt # 3070588-1434 W. 87th St. Room at the Cross Church

Attachments: Picture (Device Independent Bitmap); Picture (Device Independent Bitmap)

netCADOPS - [DRNQV] - Windows Internet Explorer provided by Exelon Corporation

http://prod-netcadops.powertools.ceco.com:2000/pls/comed_netcc/NetcMenu.TOC?p_session_id=13FA918FAF57F935

File Edit View Favorites Tools Help

netCADOPS - [DRNQV]

netCADOPS™

- Log Off
- Executive Info**
 - Overview Map
 - Overview List
 - Area Map
 - Area Outages
 - Outage Detail
 - Outage History
- Temporal Trends**
- CSR**
 - Call Entry
 - Trouble Reports
 - Non-Cust. Calls
 - Callback List
 - Notification List
- Storm Room**
 - Overview List
 - Area Outages
 - Outage Detail
 - Cust. Calls
 - Non-Cust. Calls
 - Outage History
 - Crew Management
 - Crew List
 - Employee List
 - Jobs
- Storm Mode**
- Opcon Level**
- Reports**
- Bulletins**
 - Display Bulletins
 - Create Bulletins
 - Bulletin Summary Report
- My Account**
 - Who Am I

Outage

Outage No	3070588	<input type="button" value="Query"/>	Dis
Region	CHICAGO		Sul
Business Office	CHICAGO SOUTH OC		Fer
Sub Area	CHICAGO SOUTH WEST		Phi
<hr/>			
Status	Incident Complete		Ext
Master Outage			De
Secondary Outage	No		De
Momentary Outage	No		Ad
Planned Outage	No		Fa
<hr/>			
Hazard	No		Be
Duration	7:05:30		En
Power Off	10/19/2012 10:05:30		Rel
Power On	10/19/2012 17:11:00		Co
Est. Time of Restoration	<input type="text" value="10/19/2012 20:00"/>		
Cur. Est. Time of Restor. Equipment			
	Type	Category	
	PROBABLE	Underground cable problem	
Cause	Type	Category	
	CAUSE		
Callback Method	<input checked="" type="radio"/> Manual	<input type="radio"/> Automatic	

Dispatch Time	Est. Time Arrived	Enroute
<input type="checkbox"/> Status: COMPLETE	Crew Act. ID: 4062049	Crew ID: A-Sent-to-CAD
<input type="text" value="10/19/2012 10:05"/>	<input type="text" value=""/>	<input type="text" value="10/19/2012 17:11"/>
Comments <input type="text" value=""/>		

netCADOPS - [DRNDY] - Windows Internet Explorer provided by Exelon Corporation

http://prod-netcadops.powertools.ceco.com:2000/pls/comed_netc/NetcMenu.TOC?p_session_id=13FA918FAF57F935

OutageLog - Windows Internet Explorer provided by Exelon Corporation

14	10/19/2012 14:12	Comment Addition		
Customer has been left with 120/240 for lighting and no 208 high leg. Customer has also been advise phase. CUST HAS FLT ON CUST CABLE				
13	10/19/2012 13:56	Crew Status Change	ASSIGNED	LOV
ASSIGNED BY CAD				
12	10/19/2012 13:56	Crew Status Change	DEASSIGN	LOV
CAD Updated Status				
11	10/19/2012 13:44	Comment Addition		
Customer has been left with 120/240 for lighting and no 208 high leg. Customer has also been advise phase.				
10	10/19/2012 13:29	Comment Addition		
I'm attaching photos of the faulted cable to this ticket.				
9	10/19/2012 13:29	Comment Addition		
The power transformer has a blown fuse due to the customer's secondary cable fault. The can cant b				
8	10/19/2012 13:27	PROBABLE_CAUSE_CHANGE		
Probable Cause updated in OMS				

Done

Start | [Icons]

John Valdez
 Revenue Protection
 (773) 406-2305