

**Illinois Commerce Commission
Pipeline Safety
Exit Meeting Documentation Form**

Operator:	AMEREN ILLINOIS COMPANY
Inspection Unit(s):	Jerseyville/Virden
Date of Meeting:	02/05/2016
Pipeline Safety Analyst:	Donald Hankins
Exit Meeting Contact:	Chris Juliusson

Exit Statement

INSPECTION FINDINGS

Standard Inspection - Record Audit

Issues(s) Found:

[NO ISSUES FOUND]

Notice Of Amendment(s) Found:

[NO NOAS FOUND]

Notice Of Violation(s) Found:

[NO NOPVS FOUND]

PAST INSPECTION FINDINGS

Issue(s) Corrected:

[NO ISSUES CORRECTED]

Notice Of Amendment(s) Corrected:

[NO NOAS CORRECTED]

Notice of Violations(s) Corrected:


2015-V001-00004 (Code Part [192.1005][192.1007(a)]) - Ameren Jerseyville has replaced the service line at 309 East Prairie Street in Jerseyville, this NOPV can be closed with this service line now not being isolated.

2015-V002-00004 (Code Part [192.1005][192.1007(a)]) - This NOPV can be closed Ameren Illinois in Jerseyville has replaced the isolated service line with a new plastic service line at 311 East Prairie Street, in Jerseyville

2015-V003-00004 (Code Part [192.1005][192.1007(a)]) - The service line at 319 East Prairie Street in Jerseyville has been replaced with a new plastic service line. This NOPV can be closed because it is not an isolated service line now.

2015-V004-00004 (Code Part [192.1005][192.1007(a)]) - The service line at 325 East Prairie Street in Jerseyville has been replaced with a new plastic service line. This NOPV can be closed because it is not an isolated service line now.

Pipeline Safety Analyst Signature:



Operator Representative Signature:

