

00-0714
 ICC Staff Cross 10
 8/3/01
 [Signature]

Illinois Power Company
 ICC Docket No. 00-0714
 Staff Data Request
 ENG-2.183

ENG 2.183 Aside from the information provided in response to Staff data request ENG 2.100, what other upgrades, improvements, overhauls, etc. had IP conducted at its Freeburg facility during the period 1995 through 2000?

Response

- 1995 - Installed sphere level transmitter and digital indicator
- 1996 - Replace pressure transmitter for sphere pressure indication and control
- 1997 - Replaced DC power supply for control power
 Replaced PIC 312B (add/subtract compressor steps)
 Replaced PIC 312A Transfer liquid flow controller
 Replaced 5 relief valves on process equipment
 Replaced 8 relief valves on surge drum
 Replaced 2 refrigeration vapor compressors w/rebuilt units
- 1998 - Replaced 42' of piping because of condition
 Replaced propane super heater temp. controller
 Replaced the Glycol/water heater temp. controller
 Replaced the propane injection ratio controller
 Replaced the Propane pipeline flow controller
 Replaced the flow recorded chart
 Replaced sphere pressure transmitter
- 1999 - Replaced the differential pressure switch on control room ventilation system
 Replaced refrigeration vapor compressor w/rebuilt unit
 Replaced glycol/water circulation pump
 Replaced flow switch on eg/water circulation system
- 2000 - Replace EG/H2O Pump w/rebuilt unit
 Replaced sphere relief valves
 Replace relief valves on surge tank

Prepared Under Direction of Frank Starbody
 Communication Concerning Response, Direct to:
 Barbara A. McKinney
 (217) 424-6472
 Illinois Power Company
 500 South 27th Street
 Decatur, IL 62521