

**Figure 9 (Photo 05-CE648a)**  
**3-phase primary through a Siberian elm tree,  
Union Street south of Columbia Street, Aurora**



**Figure 10 (Photo 05-CE656a)**  
**Honey locust tree grown into (over & under) 3-phase primary,  
Prairie Street west of Elmwood Avenue, Aurora**



**Figure 11 (Photo 05-CE658a)**  
**Spruce trees growing into 3-phase primary (with burning),  
Clarendon Hills Road south of 68<sup>th</sup> Street, Darien**



**Figure 12 (Photo 05-CE686a)**  
**Pin oak trees into 3-phase primary (with burning),  
84<sup>th</sup> Avenue south of 163<sup>rd</sup> Street, Tinley Park**



**Figure 13 (Photo 05-CE692a)**  
**Lombardy poplar trees through and  
engulfing 3-phase primary,  
175<sup>th</sup> St. west of Sandalwood Dr.,  
Tinley Park**




**Figure 14 (Photo 05-CE698a)**  
Primary through oak tree  
(with burning),  
Oakley N. of Lakeview Ave.,  
Joliet



**Figure 15 (Photo 05-CE724)**  
Primary through poplar trees,  
East of Bradford St. in the  
alley north of Timber St.,  
Pontiac

**Figure 16 (Photo 05-CE727a)**  
**3-phase primary through a  
silver maple tree,  
Mill St. south of North St.,  
Pontiac**



**Figure 17 (Photo 05-CE729a)**  
**Primary through elm trees,  
Plum Street between Prairie & North Streets, Pontiac**

