

APPLE CANYON UTILITY COMPANY
LAKE WILDWOOD UTILITIES CORPORATION

Docket Nos. 09-0548 and 09-0549
Responses to Lake Wildwood Association, Inc. Data Requests 1.1 through 1.60

1.59 Please provide all documents relating to the annual inspection of critical valves.

RESPONSE: Please see the following electronic files provided as attachments to the e-mail transmitting this response:

DRR1.59LW_Valve_Inspection_Cards.zip

DRR1.59LW_Valve_Cards(MES).zip

Prepared by: Michael Miller
(847) 498-6440

OFFICIAL FILE

I.C.G. DOCKET NO. 09-0548/49

ACLPOA/LWA cross Exhibit No. 3

Witness Daniel

Date 5/18/10 Reporter AAS

M.E. SIMPSON COMPANY, INC. PRO VALVE


Map Page #: LW

Client: Utilities, Inc. - Lake Wildwood - Varna, I

LW-001

Street Name: Lake Wildwood Drive

Cross Street: April Court



Valve #	LW-001	Size	4 in	Direction		Type	Gate	Max Depth	FT	Position	
Box Code		Site	Street	Last Turned	11/06/07	Turns to Close				Tech	SP/DJ
Valve Code	Excess Capacity	Material		Marking Date	Start					End	
Location	30' E. of Lake Wildwood Dr. Cl										
Northing	Easting										
Comment	Paved over										
	GPS Date										


M.R. SIMPSON COMPANY, INC. - PRO VALVE

Map Page #: 1 W

Client: Utility, Inc. - Lake Wildwood - Varco, I

Street Name: Lake Wildwood Drive

Cross Street: Clubhouse Drive (S. Leg)



Valve #: LW-002 **Size:** 18" **Direction:** Left **Type:** Cast **Max Depth:** 4 FT **Position:** Open
Box Style: Box **Site:** Parkway **Last Turned:** 11/06/07 **Turns to Close:** **Techn:** SPDA
Valve Code: Box Full of Cable **Machine Data:** Start **End:** /
Location: 12 N. of Wildwood Dr. of
 13 W. of Clubhouse Dr. of
Testing: **Empty:** **GPS Data:**

Comment: Full of debris - Tried to vacuum out box but there is metal in it

Valve #: LW-003 **Size:** 18" **Direction:** Right **Type:** Cast **Max Depth:** 4 FT **Position:** Open
Box Style: Box **Site:** Street **Last Turned:** 11/06/07 **Turns to Close:** 21.3 **Techn:** SPDA
Valve Code: Valve OK **Machine Data:** Start **End:** /
Location: 27 S. of Wildwood Dr. of
 10 W. of Clubhouse Dr. of
Testing: **Empty:** **GPS Data:**

Comment: OK

M.E. SIMPSON COMPANY, INC. - PRO-VALVE

Client: Utilities, Inc. Lake Wildwood - Varna, I


Street Name: Earl Miller Drive

Cross Street: Hidden Valley Drive

Map Page # LW

LW021

LW022



Valve #	Size	In	Direction	Type	NA Depth	FT	Position
LW-021	8	8	Street	Gate	4	FT	Open

Box Style	Box	Site	Street	Last Turned	11/06/07	Turns to Close	Tech	SP/DJ
Valve Code	Extra Valve Box	Machine Date	Start	/	End	/		

Location: 10' S. of Hidden Valley Dr. of 19' E. of Earl Miller Dr. of

Comment: Paved over

Valve #	Size	In	Direction	Type	NA Depth	FT	Position
LW-022	8	8	Parkway	Gate	4	FT	Open

Box Style	Box	Site	Parkway	Last Turned	11/06/07	Turns to Close	20.2	Tech	SP/DJ
Valve Code	Extra Valve Box	Machine Date	Start	/	End	/			

Location: 9' N. of Hidden Valley Dr. of 61' W. of Earl Miller Dr. of

Comment: Needs 2/4 inch


M.E. SIMPSON COMPANY, INC. - PRO-VALVE

Client: Utilitec, Inc. - Lake Wildwood - Varna, I

Map Page #: LW

Street Name: Brookside Drive

Cross Street: Cherry Hill Drive



Valve #	LW-039	Size	3 in	Direction		Type	Gate	Nut Depth	FT	Position	
Box Style	Box	Site	Street	Last Turned	11/07/07	Turns to Close				Tech	SP/DJ
Valve Code	Round Quad Box	Machine Data	Start	/	End	/					
Location	8' N. of Cherry Hill Dr. of 32' E. of Brookside Dr. of										
Nothing	Nothing										
Nothing	Nothing										
Nothing	Nothing										

Comment: Paved over

Valve #	LW-040	Size	3 in	Direction	Right	Type	Gate	Nut Depth	4 FT	Position	Open
Box Style	Box	Site	Parkway	Last Turned	11/07/07	Turns to Close	20.2			Tech	SP/DJ
Valve Code	Yield Dr	Machine Data	Start	/	End	/					
Location	37' N. of Cherry Hill Dr. of 18' E. of Brookside Dr. of										
Nothing	Nothing										
Nothing	Nothing										
Nothing	Nothing										

Comment: New valve on site


M.E. SIMPSON COMPANY, INC. PRO VALVE

Map Page #: LW

Client: Utilities, Inc. - Lake Wildwood - Varna, I

Street Name: Lake Wildwood Drive

Cross Street: Brookside Drive



Valve # LW-047 **Size** 8" **Direction** Right **Type** Gate **Max Depth** 4 FT **Position** Open
Box Style Box **Sho** **Last Turned** 11/07/07 **Turn to Close** **Test** SPDI
Valve Code Box BILM Data **Machine Date** Start / End /
Location 71' N. of Brookside Dr. of
 20' W. of Lake Wildwood Dr. of
Routing **Easing** **GPS Date**

Comment Tried to vacuum - Pieces of metal in box

Valve # LW-048 **Size** 8" **Direction** Right **Type** Gate **Max Depth** 3 FT **Position** Open
Box Style Box **Sho** Street **Last Turned** 11/07/07 **Turn to Close** 90.2 **Test** SPDI
Valve Code Valve DS **Machine Date** Start / End /
Location 20' N. of Brookside Dr. of
 10' E. of Lake Wildwood Dr. of
Routing **Easing** **GPS Date**

Comment OK

M.E. SIMPSON COMPANY, INC. - PRO VALVE

Client: Utilities, Inc. - Lake Wildwood - Varna, I

Map Page #: LW

Street Name: Westover Drive

LW-051


LW-052

LW-053

LW-054

LW-057

Cross Street: Lake Wildwood Drive



Valve #: LW-054	Site: In	Direction: Right	Type: Gate	Min Depth: 3 FT	Position: Closed
Box Style: Box	Site: Parkway	Last Turned: 11/07/07	Turns to Close:	Tech: SP/DJ	
Valve Code: Stub Valve - Mapped Only	Machine Data: Start: / End: /				
Location: 20 S. of Lake Wildwood Dr. of	Northing:		Easting:	GPS Date:	
	19 W. of Westover Dr. of				

Comment: Stub valve - Mapped only

Valve #: LW-055	Site: 4W	Direction: Right	Type: Gate	Min Depth: 3 FT	Position: Closed
Box Style: Box	Site: Street	Last Turned: 11/07/07	Turns to Close: 13.3	Tech: SP/DJ	
Valve Code: VALV OK	Machine Data: Start: / End: /				
Location: 33 N. of Lake Wildwood Dr. of	Northing:		Easting:	GPS Date:	
	6 W. of Westover Dr. of				

Comment: Found closed / Lift closed

Valve #: LW-058	Site: In	Direction: Right	Type: Gate	Min Depth: 3 FT	Position: Closed
Box Style: Box	Site: Parkway	Last Turned: 11/07/07	Turns to Close:	Tech: SP/DJ	
Valve Code: Stub Valve - Mapped Only	Machine Data: Start: / End: /				
Location: 20 S. of Lake Wildwood Dr. of	Northing:		Easting:	GPS Date:	
	19 W. of Westover Dr. of				

Comment: Stub valve - Mapped only


M.E. SIMPSON COMPANY, INC. - PRO VALVE

Client: **Utilities, Inc. - Lake Wildwood - Varna, I**

Map Page # **LW**

Street Name: **Key Court**

Cross Street: **Lake Wildwood Drive**



Valve # **LW-059** Size **4 in** Direction **Right** Type **Gate** Nut Depth **3 FT** Position **Open**
 Box Style **Box** Size **Street** Last Turned **11/07/07** Turns to Close **12.5** Tech **SP/DJ**
 Valve Code **Yates OK** Machine Date **Start** / / End / /
 Location **11 N. of Key Ct. (R) of**
25 E. of Lake Wildwood Dr. of
 Northing Easting GPS Date
 Comment **OK**

Valve # **LW-058** Size **4 in** Direction **Right** Type **Gate** Nut Depth **3 FT** Position **Open**
 Box Style **Box** Size **Parade** Last Turned **11/07/07** Turns to Close **12.5** Tech **SP/DJ**
 Valve Code **Box Valve Street Bank** Machine Date **Start** / / End / /
 Location **11 N. of Key Ct. (R) of**
35 W. of Lake Wildwood Dr. of
 Northing Easting GPS Date
 Comment **Box is broken**


M.E. SIMPSON COMPANY, INC. - PRO-VALVE

Map Page # LW

Client: Utilities, Inc. - Lake Wildwood - Varna, I

Street Name: Brookside Drive

Cross Street: Ivygate Court



Valve #:	LW-068	Size:	4 in	Direction:	Right	Type:	Gate	Nut Depth:	3 RT	Position:	Open
Box Style:	Box	Site:	Parkway	Last Turned:	11/09/07	Turns to Close:	13.3	Test:	SP101		
Water Code:	Sanitary/Non-Sanitary		Machine Date:	Start	/	End	/				
Location:	13' N. of Ivygate Ct. of										
	31' W. of Brookside Dr. of										
	Nothing:			Easing:				GPS Date:			
Comment:	Box is broken										

Utilities Inc.



Lake Wildwood Utilities Corp.
System

LW-01
Valve No.


Physical Street Address _____

Cross Streets _____

N/E corner of Lake Wildwood Dr. and April Ct. (in street)

County _____

Marshall

GPS Location _____

Notes Regarding Location _____

Paved over/ Burried


Inspected by _____

Bob Bishop

Date _____

6/17/2008

Manufacturer _____

unknown

Year _____

unknown

_____ Turns to Fully Open _____

Utilities Inc.



Lake Wildwood Utilities Corp.
System

LW-02
Valve No.

Physical Street Address _____

Cross Streets _____

W side of Lake Wildwood Dr. N of Clubhouse Dr.

County _____

Marshall

GPS Location _____

Notes Regarding Location _____

Clean out box

Inspected by _____

Bob Bishop

Date _____

6/17/2008

Manufacturer _____

unknown

Year _____

unknown

Turns to Fully Open _____

Utilities Inc.



Lake Wildwood Utilities Corp.
System

LW-21
Valve No.


Physical Street Address _____

Cross Streets _____

S/E corner of Hidden Valley Dr. and Earl Miller Dr. (in street)

County _____

Marshall

GPS Location _____

Notes Regarding Location _____

Paved over/Burried


Inspected by _____

Bob Bishop

Date _____

6/17/2008

Manufacturer _____

unknown

Year _____

unknown

_____ Turns to Fully Open _____

Utilities Inc.



Lake Wildwood Utilities Corp.
System

LW-39
Valve No.


Physical Street Address _____

Cross Streets N/E corner of Brookside Dr. and Cherry Hill Dr. (on Cherry Hill main)

County Marshall

GPS Location _____

Notes Regarding Location Paved over.


Inspected by Bob Bishop

Date 6/18/2008

Manufacturer unknown

Year unknown

Turns to Fully Open 20.5

Utilities Inc.

Lake Wildwood Utilities Corp.
System

LW-40
Valve No.

Physical Street Address _____

Cross Streets _____

N/E corner of Brookside Dr. and Cherry Hill Dr. (on Brookside main)

County _____

Marshall

GPS Location _____

Notes Regarding Location _____

Paved over.

Inspected by _____

Bob Bishop

Date _____

6/18/2008

Manufacturer _____

unknown

Year _____

unknown

Turns to Fully Open _____

Utilities Inc.



Lake Wildwood Utilities Corp.
System

LW-47
Valve No.



Physical Street Address

Cross Streets

N/W corner of Lake Wildwood Dr. and Brookside Dr.

County

Marshall

GPS Location

Notes Regarding Location

Clean out valve box



Inspected by

Bob Bishop

Date

6/18/2008

Manufacturer

unknown

Year

unknown

Turns to Fully Open

Utilities Inc.

Lake Wildwood Utilities Corp.
System

LW-55
Valve No.

Physical Street Address

Cross Streets

County

GPS Location

Notes Regarding Location

On Westover Dr. at Lake Wildwood Dr.

Marshall

Valve is stub valve only/buried

Inspected by

Bob Bishop

Date

6/18/2008

Manufacturer

unknown

Year

unknown

Turns to Fully Open

13.5

Utilities Inc.



Lake Wildwood Utilities Corp.
System

LW-56
Valve No.


Physical Street Address _____

Cross Streets _____

West valve across from Westover Dr.

County _____

Marshall

GPS Location _____

Notes Regarding Location _____

Valve is stub valve only/burried


Inspected by _____

Bob Bishop

Date _____

6/18/2008

Manufacturer _____

unknown

Year _____

unknown

_____ Turns to Fully Open _____

Utilities Inc.



Lake Wildwood Utilities Corp.
System

LW-60
Valve No.



Physical Street Address _____

Cross Streets N/W corner of Key Ct. S and Lake Wildwood Dr.

County Marshall

GPS Location _____

Notes Regarding Location Valve Box needs repair



Inspected by Bob Bishop Date 6/18/2008

Manufacturer unknown Year unknown

_____ Turns to Fully Open 12.5

Utilities Inc.



Lake Wildwood Utilities Corp.
System

LW-61
Valve No.


Physical Street Address

Cross Streets

N/E corner of Lake Wildwood Dr. and Shoreline Dr.

County

Marshall

GPS Location

Notes Regarding Location

Box needs repair


Inspected by

Bob Bishop

Date

6/18/2008

Manufacturer

unknown

Year

unknown

Turns to Fully Open

20.5

Utilities Inc.

Lake Wildwood Utilities Corp.
System

LW-66
Valve No.

Physical Street Address _____
Cross Streets **NW corner of Brookside Ct and Ivygate Ct.**
County **Marshall**
GPS Location _____
Notes Regarding Location **Paved over.**

Inspected by **Bob Bishop** Date **6/18/2008**
Manufacturer **unknown** Year **unknown**
Turns to Fully Open **13.5**