

Illinois Commerce Commission

Pipeline Safety

Pipeline Safety Report

Inspection #: 2015-P-00188

Operator: AMEREN ILLINOIS COMPANY	Operator ID#: 32513
Exit Meeting Contact: Bob Roth	Total Man Days: 1
Pipeline Safety Representative(s): Jim Watts	
Company Representative to Receive Report: Michael Fuller	<b>Emailed Date:</b>
Company Representative's Email Address: mfuller2@ameren.com	06/17/2015

**Inspection Summary**

Inspection Type	Location	ICC Analyst	Inspection Unit(s)	Man Day(s)	Inspection Date(s)	Contact(s)
Integrity Management Field Audit	Greenville - Glen Carbon	Jim Watts	Decatur Plaza	1	4/29/2015	Bob Roth

**Statement of Activities**

On April 29, 2015, Staff observed a pig run being conducted by Ameren Illinois from the Greenville Station located southwest of Greenville, Illinois, to Peters 2 Station located near Glen Carbon, Illinois. The pig run was conducted as part of their Transmission Integrity Program utilizing a TDW Magnetic Flux pig to detect piping anomalies on the 37 miles of 10 inch piping. The audit was conducted to determine compliance with applicable IL Adm. Codes and the Code of Federal Regulations adopted via IL Adm. Part 590.

**Exit Statement**

**INSPECTION FINDINGS**

**Integrity Management Field Audit**

**Issues(s) Found:**

[NO ISSUES FOUND]

**Notice Of Amendment(s) Found:**

[NO NOAS FOUND]

**Notice Of Violation(s) Found:**

[NO NOPVS FOUND]

**PAST INSPECTION FINDINGS**

**Issue(s) Corrected:**

[NO ISSUES CORRECTED]

**Notice Of Amendment(s) Corrected:**

[NO NOAS CORRECTED]

**Illinois Commerce Commission  
Pipeline Safety  
Pipeline Safety Report**

***Inspection #: 2015-P-00188***

**Notice of Violations(s) Corrected:**

**[NO NOPVS CORRECTED]**