



U.S. DOT#: 079533G					Warning Device Description			
General Information					Type of Device: AFLS/Gates			
Type Of Crossing: AtGrade					Number Of Devices:			
Lat: 41° 47' 44" Long: 87° 59' 55"					CrossBucks:	2	Cantelever:	0
County: DU PAGE					Bells:	1	Gates:	2
City: DOWNERS GROVE In/Near: In					WigWags:	0	Pedestrian Gates:	2
Street Name: MAPLE AVE					Flashing Lights Pairs:	4	Masts:	4
RailRoad: BNSF					Mast Locations Edge of Road (Ft) Edge of Rail (Ft)			
RailRoad Station: FAIRVIEW AVE (E)					N	22.1	14.4	
RailRoad Milepost: 20.59					N	8	43.4	
Crossing Angle: 26.0°					W	9.4	16.5	
Data Collection Date: 7/24/2003					S	4.8	60.8	
Aerial Photography Date: Spring 2003					Track Description			
Nearest Intersecting Roads					Number of Tracks: 3			
Name	Distance (Ft)	Width (Ft)	Direction	Traffic Control	(Type of Tracks: Main)			
BURLINGTON	117.1	21.5	South West	Stop Sign	From	To	Distance (Ft)	
BLODGETT	252.2	27.3	South West	Stop Sign	Track 1	Track 2	14.4	
Number of Other Nearby Intersecting Roads: None					Track 2	Track 3	14.9	
North East Nearby Warning Signs					Adjacent Railroad Crossing			
Type	Distance (Ft)	ER	Type	Distance (Ft)	DOT#	Direction	Distance (Ft)	
W10-1	331.2		W10-1	214.1				
Number of Other Signs: 0					Number of Other Signs: 0			
North West Side		Roadway Material & Dimensions			South East Side			
		Roadway Material: Bituminous						
Dir	Dist NR	Sidewalk	Parkway	Road Width	Parkway	Sidewalk		
NE	32.0	5.0	14.5	25.0	0.0	0.0		
SW	32.0	5.8	7.8	25.6	0.0	0.0		
North West Side of Road:		Crossing Surface Material & Dimensions			South East Side of Road:			
		Distance			Distance			
Sidewalk Material	Sidewalk to Width (Ft)	Sidewalk	Roadway Material	Roadway to Width (Ft)	Sidewalk	Sidewalk	Total Crossing Width (Ft)	
Track1	Timber	9.4	0(*)	Rubber	103	0(*)	None 0 112.4	
Track2	Asphalt and Flange	10.1	0(*)	Rubber	108.3	0(*)	None 0 118.4	
Track3	Timber	4.8	0(*)	Rubber	112.8	0(*)	None 0 117.6	
North East Side		Vertical Profile			South West Side			
A-50	A-32	Track1	Track2	Track3	B-32	B-50		
1.67%	0.94%	-0.71%	-0.67%	-3.12%	-10%			
Special Conditions? None					Missing Data? No			

