



| | | | | | |
|--------------------------|-------------------------------|--|---|---------------|---------------|
| U.S. DOT#: 163438P | | | Track Description | | |
| General Information | | | Number of Tracks: 2 (Type of Tracks: Main) | | |
| Type Of Crossing: | RROver Highway | | From | To | Distance (Ft) |
| Lat: | 41° 44' 34" Long: 87° 41' 14" | | Track 1 | Track 2 | 13.0 |
| County: | COOK | | Vertical Clearance | | |
| City: | CHICAGO In/Near: In | | Minimum Vertical Clearance: 13.6 (Ft) | | |
| Street Name: | 83RD | | Horizontal Roadway Clearance | | |
| RailRoad: | CSX | | Dir | Distance (Ft) | |
| RailRoad Station: | 82ND ST (N) | | Hor Clear 1 | 46.0 | |
| RailRoad Milepost: | 21.57 | | | | |
| Crossing Angle: | 66.6° | | | | |
| IDOT Structure Number: | CDOT-289A | | | | |
| RR Structure Number: | 21.57 | | | | |
| Data Collection Date: | 10/15/2002 | | | | |
| Aerial Photography Date: | Spring 2002 | | | | |



163438P-2292004-4.jpg -- Vreasons

6- Too Many Cars on Tracks

| | | | | | | |
|--------------------------|----------|-------------------------------|---|---------|-----------------|------|
| North East Side | | Roadway Material & Dimensions | | | South West Side | |
| | | Roadway Material: Bituminous | | | | |
| Dir | Sidewalk | Parkway | Road Width | Parkway | Sidewalk | |
| Under Bridge | 10.0 | 0.0 | 46.0 | 10.0 | 0.0 | |
| North West Side | | Vertical Profile | | | South East Side | |
| A-50 | | A-25 | A-0 | B-0 | B-25 | B-50 |
| -0.4% | | 0.4% | -0.29% | 0% | 0.8% | |
| Special Conditions? None | | | Missing Data? Yes (Too Many Cars on Tracks) | | | |

