



U.S. DOT#: 175003E					Warning Device Description				
General Information Type Of Crossing: AtGrade Lat: 41° 53' 5" Long: 88° 23' 6" County: KANE City: GENEVA In/Near: Near Street Name: BRUNDIGE RD RailRoad: UP RailRoad Station: RANDALL (E) RailRoad Milepost: 39.4 Crossing Angle: 87.3° Data Collection Date: 7/14/2003 Aerial Photography Date: Spring 2003					Type of Device: Cant AFLS/Gates/Sidelights Number Of Devices: CrossBucks: 2 Cantelever: 1 Bells: 1 Gates: 2 WigWags: 0 Pedestrian Gates: 0 Flashing Lights Pairs: 4 Masts: 1				
					Mast Locations Edge of Road (Ft) Edge of Rail (Ft)				
					NW	8.5	13.6		
					SE	7.1	10		
Nearest Intersecting Roads					Track Description				
Name	Distance (Ft)	Width (Ft)	Direction	Traffic Control	Number of Tracks: 2 (Type of Tracks: Main)				
TEMP CONSTRUCTION ACCESS ROAD	31.1	25.5	South	Stop Sign	From	To	Distance (Ft)		
Number of Other Nearby Intersecting Roads: None					Track 1	Track 2	13.3		
North Nearby Warning Signs South					Adjacent Railroad Crossing				
Type	Distance (Ft)	ER	Type	Distance (Ft)	ER	DOT#	Direction	Distance (Ft)	
R15-2	13.6		R15-2	10.0					
			W10-1	473.8					
Number of Other Signs: 0					Number of Other Signs: 0				
West Side		Roadway Material & Dimensions				East Side			
		Roadway Material: Gravel							
Dir	Dist NR	Sidewalk	Parkway	Road Width	Parkway	Sidewalk			
N	32.0	0.0	0.0	17.7	0.0	0.0			
S	32.0	0.0	0.0	15.9	0.0	0.0			
West Side of Road:		Crossing Surface Material & Dimensions				East Side of Road:			
	Sidewalk Material	Sidewalk Width (Ft)	Distance to Sidewalk	Roadway Material	Roadway Width (Ft)	Distance to Sidewalk	Sidewalk Material	Sidewalk Width (Ft)	Total Crossing Width (Ft)
Track1	none	0	1.7	Rubber	24	2	none	0	27.7
Track2	none	0	1.3	Rubber	30	1.6	none	0	32.9
North Side			Vertical Profile				South Side		
A-0	A-18	A-50	T-63	B-95	B-113				
7.78%		4.06%	1.54%	-3.13%	-5%				
Special Conditions? None					Missing Data? No				

