



U.S. DOT#: 372147B					Warning Device Description				
General Information					Type of Device: X-Bucks				
Type Of Crossing: AtGrade					Number Of Devices:				
Lat: 41° 56' 10" Long: 87° 53' 38"					CrossBucks: 1 Cantelever: 0				
County: COOK					Bells: 0 Gates: 0				
City: FRANKLIN PARK In/Near: In					WigWags: 0 Pedestrian Gates: 0				
Street Name: BELMONT AVE.					Flashing Lights Pairs: 0 Masts: 1				
RailRoad: SOO					Mast Locations Edge of Road (Ft) Edge of Rail (Ft)				
RailRoad Station: MANNHEIM (N)					N 7.5 17.5				
RailRoad Milepost: 14.21									
Crossing Angle: 76.5°									
Data Collection Date: 9/11/2002									
Aerial Photography Date: Spring 2002									
Nearest Intersecting Roads					Track Description				
Name	Distance (Ft) ER	Width (Ft)	Direction	Traffic Control	Number of Tracks: 1 (Type of Tracks: Main)				
LEE	183.0	25.0	South West	Stop Sign	From	To	Distance (Ft)		
Number of Other Nearby Intersecting Roads: None					None				
South West Nearby Warning Signs North East					Adjacent Railroad Crossing				
Type	Distance (Ft) ER	Type	Distance (Ft) ER	DOT#	Direction	Distance (Ft)			
W10-1	143.0	W10-1	180.0						
Number of Other Signs: 0					Number of Other Signs: 0				
North West Side		Roadway Material & Dimensions				South East Side			
		Roadway Material: Bituminous							
Dir	Dist NR	Sidewalk	Parkway	Road Width	Parkway	Sidewalk			
SW	32.0	0.0	0.0	30.0	0.0	0.0			
NE	32.0	0.0	0.0	29.5	0.0	0.0			
South East Side of Road:			Crossing Surface Material & Dimensions				North West Side of Road:		
							Total		
	Sidewalk Material	Sidewalk Width (Ft)	Distance to Sidewalk	Roadway Material	Roadway Width (Ft)	Distance to Sidewalk	Sidewalk Material	Sidewalk Width (Ft)	Crossing Width (Ft)
Track1	None	0	0(*)	Asphalt	43.5	0(*)	None	0	43.5
South West Side		Vertical Profile				North East Side			
A-50		A-32		Track1		B-32		B-50	
2.78%		3.44%		-1.56%		0.56%			
Special Conditions? None					Missing Data? No				

