



U.S. DOT#: 8000020					Warning Device Description				
General Information					Type of Device: X-Bucks				
Type Of Crossing: AtGrade					Number Of Devices:				
Lat: 41° 56' 38" Long: 87° 54' 38"					CrossBucks:	2	Cantelever:	0	
County: COOK					Bells:	0	Gates:	0	
City: FRANKLIN PARK In/Near:					WigWags:	0	Pedestrian Gates:	0	
Street Name: RUNGE AVE.					Flashing Lights Pairs:	0	Masts:	2	
RailRoad: SOO					Mast Locations				
RailRoad Station: BENSENVILLE YD (N)					Edge of Road (Ft)	Edge of Rail (Ft)			
RailRoad Milepost: 0					NW	8.2	5.5		
Crossing Angle: 89.9°					SE	6.6	6		
Data Collection Date: 8/13/2002									
Aerial Photography Date: Spring 2002									
Nearest Intersecting Roads					Track Description				
Name	Distance (Ft) ER	Width (Ft)	Direction	Traffic Control	Number of Tracks: 2 (Type of Tracks: Main)				
Number of Other Nearby Intersecting Roads: None					From	To	Distance (Ft)		
					Track 1	Track 2	17.0		
North		Nearby Warning Signs			South		Adjacent Railroad Crossing		
Type	Distance (Ft) ER	Type	Distance (Ft) ER	DOT#	Direction	Distance (Ft)			
Number of Other Signs: 0		Number of Other Signs: 0							
West Side		Roadway Material & Dimensions				East Side			
		Roadway Material: Bituminous							
Dir	Dist NR	Sidewalk	Parkway	Road Width	Parkway	Sidewalk			
N	32.0	0.0	0.0	24.0	0.0	0.0			
S	32.0	0.0	0.0	24.0	0.0	0.0			
West Side of Road:		Crossing Surface Material & Dimensions				East Side of Road:			
		Sidewalk		Roadway		Total			
	Sidewalk Width	Distance to Roadway	Width	Distance to Sidewalk	Sidewalk Width	Crossing Width			
	Material (Ft)	Sidewalk Material	(Ft)	Sidewalk Material	(Ft)	(Ft)			
Track1	None	0	0(*)	Asphalt and Flange	29	0(*)	None	0	29
Track2	None	0	0(*)	Asphalt and Flange	27.5	0(*)	None	0	27.5
North Side		Vertical Profile				South Side			
A-50		A-32	Track1	Track2	B-32	B-50			
0%		0%	0.59%	-0.31%	0.56%				
Special Conditions? None				Missing Data? No					

