



U.S. DOT#: 372167M				Warning Device Description							
General Information Type Of Crossing: AtGrade Lat: 41° 58' 14" Long: 87° 57' 12" County: DU PAGE City: BENSENVILLE In/Near: In Street Name: COUNTRY CLUB DR RailRoad: SOO RailRoad Station: BENSENVILLE TV (S) RailRoad Milepost: 0.36 Crossing Angle: 88.6° Data Collection Date: 7/24/2003 Aerial Photography Date: Spring 2003				Type of Device: X-Bucks Number Of Devices: CrossBucks: 2 Cantelever: 0 Bells: 0 Gates: 0 WigWags: 0 Pedestrian Gates: 0 Flashing Lights Pairs: 0 Masts: 2							
				Mast Locations Edge of Road (Ft) Edge of Rail (Ft)							
				NW 7.6 9.1 SE 20 10.2							
Nearest Intersecting Roads				Track Description							
Name	Distance (Ft) ER	Width (Ft)	Direction	Traffic Control	Number of Tracks: 2 (Type of Tracks: Siding)						
Number of Other Nearby Intersecting Roads: None				From To Distance (Ft) Track 1 Track 2 8.3							
Nearby Warning Signs				Adjacent Railroad Crossing							
North	Type	Distance (Ft) ER	South	Type	Distance (Ft) ER	DOT#	Direction	Distance (Ft)			
	W10-1	301.5		W10-1	122.0						
Number of Other Signs: 0				Number of Other Signs: 0							
West Side		Roadway Material & Dimensions				East Side					
		Roadway Material: Bituminous									
Dir	Dist NR	Sidewalk	Parkway	Road Width	Parkway	Sidewalk					
N	32.0	0.0	0.0	34.7	0.0	0.0					
S	32.0	0.0	0.0	34.6	0.0	0.0					
West Side of Road:		Crossing Surface Material & Dimensions				East Side of Road:					
		Sidewalk		Roadway		Total					
	Sidewalk Width	Distance to Roadway	Width	Distance to Sidewalk	Sidewalk Width	Crossing					
	Material (Ft)	Sidewalk Material	(Ft)	Sidewalk Material	(Ft)	Width (Ft)					
Track1	None	0	0(*)	Asphalt and Flange	41.5	0(*)	None	0	41.5		
Track2	None	0	0(*)	Asphalt and Flange	41.3	0(*)	None	0	41.3		
North Side		Vertical Profile				South Side					
A-50		A-32		Track1		Track2		B-32		B-50	
0%		0%		1.25%		0.62%		1.11%			
Special Conditions? None				Missing Data? No							

