



U.S. DOT#: 386439N				Warning Device Description																											
General Information Type Of Crossing: AtGrade Lat: 42° 20' 40" Long: 88° 4' 19" County: LAKE City: HAINESVILLE In/Near: In Street Name: BELVIDERE RD RailRoad: NIRC RailRoad Station: ROUND LAKE (NW) RailRoad Milepost: 42.6 Crossing Angle: 49.3° Data Collection Date: 9/30/2003 Aerial Photography Date: Spring 2003				Type of Device: AFLS/Gates Number Of Devices: CrossBucks: 2 Cantelever: 0 Bells: 1 Gates: 2 WigWags: 0 Pedestrian Gates: 0 Flashing Lights Pairs: 4 Masts: 2																											
				Mast Locations Edge of Road (Ft) Edge of Rail (Ft)																											
				S 8.5 28																											
				N 6.8 23.5																											
Nearest Intersecting Roads <table border="1"> <thead> <tr> <th>Name</th> <th>Distance (Ft) ER</th> <th>Width (Ft)</th> <th>Direction</th> <th>Traffic Control</th> </tr> </thead> <tbody> <tr> <td colspan="5">Number of Other Nearby Intersecting Roads: None</td> </tr> </tbody> </table>				Name	Distance (Ft) ER	Width (Ft)	Direction	Traffic Control	Number of Other Nearby Intersecting Roads: None					Track Description Number of Tracks: 1 (Type of Tracks: Main)																	
Name	Distance (Ft) ER	Width (Ft)	Direction	Traffic Control																											
Number of Other Nearby Intersecting Roads: None																															
				<table border="1"> <thead> <tr> <th>From</th> <th>To</th> <th>Distance (Ft)</th> </tr> </thead> <tbody> <tr> <td colspan="3">None</td> </tr> </tbody> </table>			From	To	Distance (Ft)	None																					
From	To	Distance (Ft)																													
None																															
<table border="1"> <thead> <tr> <th>South West</th> <th>Nearby Warning Signs</th> <th>North East</th> </tr> <tr> <th>Type</th> <th>Distance (Ft) ER</th> <th>Type</th> <th>Distance (Ft) ER</th> </tr> </thead> <tbody> <tr> <td>R8-8</td> <td>39.0</td> <td>W10-1</td> <td>367.0</td> </tr> <tr> <td>W10-1</td> <td>305.0</td> <td></td> <td></td> </tr> <tr> <td colspan="2">Number of Other Signs: 0</td> <td colspan="2">Number of Other Signs: 0</td> </tr> </tbody> </table>				South West	Nearby Warning Signs	North East	Type	Distance (Ft) ER	Type	Distance (Ft) ER	R8-8	39.0	W10-1	367.0	W10-1	305.0			Number of Other Signs: 0		Number of Other Signs: 0		Adjacent Railroad Crossing <table border="1"> <thead> <tr> <th>DOT#</th> <th>Direction</th> <th>Distance (Ft)</th> </tr> </thead> <tbody> <tr> <td colspan="3"></td> </tr> </tbody> </table>			DOT#	Direction	Distance (Ft)			
South West	Nearby Warning Signs	North East																													
Type	Distance (Ft) ER	Type	Distance (Ft) ER																												
R8-8	39.0	W10-1	367.0																												
W10-1	305.0																														
Number of Other Signs: 0		Number of Other Signs: 0																													
DOT#	Direction	Distance (Ft)																													
North West Side		Roadway Material & Dimensions			South East Side																										
Roadway Material: Bituminous																															
Dir	Dist NR	Sidewalk	Parkway	Road Width	Parkway	Sidewalk																									
SW	32.0	0.0	0.0	25.2	0.0	0.0																									
NE	32.0	0.0	0.0	25.5	0.0	0.0																									
North West Side of Road:		Crossing Surface Material & Dimensions				South East Side of Road:																									
						Total																									
	Sidewalk Material	Sidewalk Width (Ft)	Distance to Sidewalk	Roadway Material	Roadway Width (Ft)	Distance to Sidewalk	Sidewalk Material	Sidewalk Width (Ft)	Crossing Width (Ft)																						
Track1	None	0	0(*)	Rubber	45	0(*)	None	0	45																						
South West Side		Vertical Profile				North East Side																									
A-50		A-32		Track1		B-32		B-50																							
2.78%		2.81%		-0.63%		-1.67%																									
Special Conditions? None				Missing Data? No																											

