



U.S. DOT#: 608220E					Warning Device Description			
General Information Type Of Crossing: AtGrade Lat: 41° 30' 15" Long: 88° 6' 52" County: WILL City: ROCKDALE In/Near: In Street Name: MIDLAND AVE RailRoad: CSX RailRoad Station: ROCKDALE (W) RailRoad Milepost: 42.6 Crossing Angle: 44.3° Data Collection Date: 7/30/2003 Aerial Photography Date: Spring 2003					Type of Device: AFLS/Gates Number Of Devices: CrossBucks: 2 Cantelever: 0 Bells: 1 Gates: 2 WigWags: 0 Pedestrian Gates: 0 Flashing Lights Pairs: 4 Masts: 2			
					Mast Locations Edge of Road (Ft) Edge of Rail (Ft)			
					NW 8.4 9.3 SE 6.5 9.7			
Nearest Intersecting Roads					Track Description			
Name	Distance (Ft) ER	Width (Ft)	Direction	Traffic Control	Number of Tracks: 3 (Type of Tracks: Siding, Main)			
MOEN AV	346.0	42.1	North	Stop Sign	From	To	Distance (Ft)	
Number of Other Nearby Intersecting Roads: None					Track 1	Track 2	16.2	
					Track 2	Track 3	13.8	
North Nearby Warning Signs South					Adjacent Railroad Crossing			
Type	Distance (Ft) ER	Type	Distance (Ft) ER	DOT#	Direction	Distance (Ft)		
W10-1	185.0	W10-1	293.0					
Number of Other Signs: 0					Number of Other Signs: 0			
West Side		Roadway Material & Dimensions				East Side		
		Roadway Material: Bituminous						
Dir	Dist NR	Sidewalk	Parkway	Road Width	Parkway	Sidewalk		
N	32.0	0.0	0.0	21.9	0.0	0.0		
S	32.0	0.0	0.0	22.4	0.0	0.0		
West Side of Road:		Crossing Surface Material & Dimensions				East Side of Road:		
	Sidewalk Material	Sidewalk Width (Ft)	Distance to Sidewalk	Roadway Material	Roadway Width (Ft)	Distance to Sidewalk	Sidewalk Material	Total Crossing Width (Ft)
Track1	None	0	0(*)	Asphalt	27	0(*)	None	27
Track2	None	0	0(*)	Full Wood Plank	30	0(*)	None	30
Track3	None	0	0(*)	Other	31.8	0(*)	None	31.8
North Side		Vertical Profile				South Side		
A-50	A-32	Track1	Track2	Track3	B-32	B-50		
2.78%	0.63%	0.62%	1.43%	-4.69%	-2.22%			
Special Conditions? None					Missing Data? No			

