



U.S. DOT#: 689697G					Warning Device Description				
General Information					Type of Device: Cant AFLS/Gates				
Type Of Crossing: AtGrade					Number Of Devices:				
Lat: 42° 13' 15" Long: 87° 58' 3"					CrossBucks: 2		Cantelever: 2		2
County: LAKE					Bells: 1		Gates: 2		2
City: VERNON HILLS In/Near: Near					WigWags: 0		Pedestrian Gates: 0		0
Street Name: US HIGHWAY 45					Flashing Lights Pairs: 8		Masts: 4		4
RailRoad: WC					Mast Locations Edge of Road (Ft) Edge of Rail (Ft)				
RailRoad Station: VERNON HILLS (S)					SW 5.8		40.3		
RailRoad Milepost: 36.05					SW 6		37.5		
Crossing Angle: 22.9°					NE 5.7		30		
Data Collection Date: 6/26/2003					NE 5.6		25.4		
Aerial Photography Date: Spring 2003									
Nearest Intersecting Roads					Track Description				
Name	Distance (Ft) ER	Width (Ft)	Direction	Traffic Control	Number of Tracks: 1 (Type of Tracks: Main)				
DEERPATH DR	310.0	38.4	East	Stop Sign	From	To	Distance (Ft)		
Number of Other Nearby Intersecting Roads: None					None				
West Nearby Warning Signs					East				
Type	Distance (Ft) ER	Type	Distance (Ft) ER	DOT#	Direction		Distance (Ft)		
R8-8	46.4	R8-8	61.1						
W10-1	364.0	R8-8	74.4						
Number of Other Signs: 0					Number of Other Signs: 0				
North Side			Roadway Material & Dimensions				South Side		
			Roadway Material: Bituminous						
Dir	Dist NR	Sidewalk	Parkway	Road Width	Parkway	Sidewalk			
W	32.0	5.6	7.2	36.4	0.0	0.0			
E	32.0	5.0	7.9	35.6	0.0	0.0			
North Side of Road:			Crossing Surface Material & Dimensions				South Side of Road:		
							Total		
	Sidewalk Material	Sidewalk Width (Ft)	Distance to Sidewalk	Roadway Material	Roadway Width (Ft)	Distance to Sidewalk	Sidewalk Material	Sidewalk Width (Ft)	Crossing Width (Ft)
Track1	None	0	20.2	Rubber	127	0(*)	None	0	147.2
West Side			Vertical Profile				East Side		
A-50			Track1				B-50		
0.56%			0%				-1.56%		
							-1.11%		
Special Conditions? None					Missing Data? No				

