



| | | | | | | | | | | | | | | |
|---|-----------------------|----------------------|------------------|--------------------|--|-------------------|---------------------|---------------------------|--|---------------------|--|--|--|--|
| U.S. DOT#: 8000180 | | | | | Warning Device Description | | | | | | | | | |
| General Information | | | | | Type of Device: None | | | | | | | | | |
| Type Of Crossing: | | | | | Number Of Devices: | | | | | | | | | |
| Lat: 41° 55' 3" Long: 87° 54' 48" | | | | | CrossBucks: 0 Cantelever: 0 | | | | | | | | | |
| County: COOK | | | | | Bells: 0 Gates: 0 | | | | | | | | | |
| City: NORTHLAKE In/Near: | | | | | WigWags: 0 Pedestrian Gates: 0 | | | | | | | | | |
| Street Name: RAILROAD AVE. | | | | | Flashing Lights Pairs: 0 Masts: 0 | | | | | | | | | |
| RailRoad: | | | | | Mast Locations Edge of Road (Ft) Edge of Rail (Ft) | | | | | | | | | |
| RailRoad Station: PROVISO YD NORTH (At) | | | | | | | | | | | | | | |
| RailRoad Milepost: | | | | | | | | | | | | | | |
| Crossing Angle: 47.4° | | | | | | | | | | | | | | |
| Data Collection Date: 9/18/2002 | | | | | | | | | | | | | | |
| Aerial Photography Date: Spring 2002 | | | | | | | | | | | | | | |
| Nearest Intersecting Roads | | | | | Track Description | | | | | | | | | |
| Name | Distance (Ft) ER | Width (Ft) | Direction | Traffic Control | Number of Tracks: 0 (Type of Tracks:) | | | | | | | | | |
| Number of Other Nearby Intersecting Roads: None | | | | | From | To | Distance (Ft) | | | | | | | |
| | | | | | None | | | | | | | | | |
| Nearby Warning Signs | | | | | Adjacent Railroad Crossing | | | | | | | | | |
| East | Type Distance (Ft) ER | | | West | DOT# | Direction | Distance (Ft) | | | | | | | |
| Number of Other Signs: 0 | | | | | Number of Other Signs: 0 | | | | | | | | | |
| North Side | | | | | Roadway Material & Dimensions | | | | | South Side | | | | |
| | | | | | Roadway Material: | | | | | | | | | |
| Dir | Sidewalk | Parkway | Road Width | | Parkway | Sidewalk | | | | | | | | |
| North Side of Road: | | | | | Crossing Surface Material & Dimensions | | | | | South Side of Road: | | | | |
| | | | | | Total | | | | | | | | | |
| Sidewalk Material | Sidewalk Width (Ft) | Distance to Sidewalk | Roadway Material | Roadway Width (Ft) | Distance to Sidewalk | Sidewalk Material | Sidewalk Width (Ft) | Total Crossing Width (Ft) | | | | | | |
| No Tracks Found | | | | | | | | | | | | | | |
| East Side | | | | | Vertical Profile | | | | | West Side | | | | |
| No Profiles Found | | | | | | | | | | | | | | |
| Special Conditions? None | | | | | Missing Data? Yes (Not Sure Where Crossing Is) | | | | | | | | | |

