



|                                      |                                   |   |                  |
|--------------------------------------|-----------------------------------|---|------------------|
| U.S. DOT#: 843804S                   |                                   | Track Description                             |                  |
| General Information                  |                                   | Number of Tracks: 2<br>(Type of Tracks: Main) |                  |
| Type Of Crossing: RRUnder Highway    | Lat: 41° 49' 7" Long: 87° 44' 19" | From  | To Distance (Ft) |
| County: COOK                         | City: CHICAGO In/Near: In         | Track 1                                       | Track 2 14.1     |
| Street Name: STEVENSON EXPR          | RailRoad: BRC                     | Vertical Clearance                            |                  |
| RailRoad Station: LEMOYNE (S)        | RailRoad Milepost: 6.68           | Minimum Vertical Clearance: (Ft)              |                  |
| Crossing Angle: 69.6°                | IDOT Structure Number:            | Horizontal Track Clearance                    |                  |
| RR Structure Number:                 | Data Collection Date: 10/9/2002   | From  | To Distance (Ft) |
| Aerial Photography Date: Spring 2002 |                                   |   |                  |
| [Pictures Missing]                   |                                   | [Pictures Missing]                            |                  |
| [Pictures Missing]                   |                                   | [Pictures Missing]                            |                  |
| North Side                           | Roadway Material & Dimensions     | South Side                                    |                  |
| Dir                                  | Roadway Material: Bituminous      | Parkway                                       | Sidewalk         |
| Sidewalk                             | Road Width                        | Parkway                                       | Sidewalk         |
|                                      |                                   |   |                  |
| West Side                            | Vertical Profile                  | East Side                                     |                  |
| No Profiles Found                    |                                   |   |                  |
| Special Conditions? None             |                                   | Missing Data? Yes (Highway Access Issues)     |                  |

